HPC Application No. HPC2022/186 – Block 147 Lot 14 25 Olin St K. Williamson HPC Hearing February 14, 2023

Notes:

- The condenser has been placed in the space that shows as a shed on the survey (see Survey pages 3-4). That
 shed was a frame and plywood cover for an above ground oil tank that was removed in 2006 when we replaced
 the furnace and added central air conditioning. In doing so, we have no essentially altered the exterior of the
 house.
 - Plumbing and electrical permits were approved but no HPC approval was requested at that time this was an oversight. Our original contractor Larrison's in Neptune City –handled all permits and permissions. I was unaware of the HPC at that time and did not know that HPC approval was also needed. (Please refer to pages 5-6 containing permit information for Project 31655 Issued April 17, 2006 and approvals dated May 10 18, 2006)
 - o The condenser unit was installed in 2006 in the side yard, in a small pocket area between the fence and the front side of the bumpout (*Photo #1, p7*). This keeps the unit out of the flow of foot traffic in the yard, so it is both well protected and not a hazard for people using the side and back yard.
 - The view of the unit from the street is shielded by the fence. Should a subsequent owner decide to remove the fence, it could easily be screened by planting.
 - While we recognize that a fence is a temporary structure, please note that the fence in place now was installed in 2007 (with HPC approval at that time). It is structurally sound, although we are considering replacing it in the coming months with an approved style that would be easier to maintain. We have every intention of keeping a fence in place.
 - The life expectancy of an AC condenser in a shore area is about 12-14 years. The current fence has already held up better than that.
 - The current condenser unit is much smaller than the one installed in 2006 the length and width are about half that of the original unit. The original unit was also considerably smaller than the shed/oil tank originally in that spot. Aesthetically, these have both been an improvement over what was in place when we purchased the house.
 - Photo 2, p8 is taken from about the middle of the driveway and shows the fence in front of the
 condenser unit as you can see, the unit is completely screened by the fence and entirely out of view
 from the sidewalk.
 - Photo 3: Rear side of the bumpout with silver tape on the pavers marked to show length and width of the condenser unit if it were installed 11" from the side of the house. It is currently situated 11" from the side of the house, so I used that same measurement here. That space is needed to allow for the various connections and fittings. The condenser unit is also 31" tall.
 - The crawl space access panel is visible in this photo.


Please refer to Drawing p10

- o Drawing, p10: Bumpout dimensions including the location of the back door and mechanicals inside
- The bumpout is essentially a utility room and a passthrough between the backdoor and the kitchen. It allows for a second means of egress. All the mechanicals for the house hot water heater, furnace/air handler and electrical panel) are in the bumpout to the right of the backdoor, the side nearest the street.

- There is no access to go under the bumpout as this was part of the house built on a slab and appears to have been added separately from the one story addition identified on the survey. The rest of the house sits on a crawlspace.
- Moving the AC condenser to sit behind the bumpout creates several problems:
 - The crawlspace panel is occasionally needed for plumbing repairs. As it is, the plumber has had to send their shortest person to service our property when it has been necessary to go into the crawlspace.
 - To access the crawlspace, the plumber has to sit on the ground and lean back to slowly lower himself feet first through the opening. Locating the condenser on the rear side of the bumpout would make it extremely difficult, if at all possible, to safely enter and exit the crawlspace.
 - Placing the condenser on the back side of the bumpout would compromise safe access to the crawlspace, and without access via the crawlspace, the only way to get at gas, water and drain lines in the kitchen will be to pull up the kitchen floor.
 - Switching the fittings for the electrical connection and air handler to run through the space leading to the kitchen rather than where it sits now would be highly impractical. Connections would need to run through this area, which is a means of egress from the kitchen in the event of a fire.

While the placement of the condenser unit is not strictly compliant with current HPC guidelines, the present location of the AC unit is the safest and most practical, and, equally importantly, we are able to fully maintain the spirit of the guidelines by shielding the unit from the streetside view with the fence.

For these reasons we respectfully ask that you please consider granting permission for us to proceed with the AC unit where it is placed.



*

O RIGHT OF WAY

25' PAVEMENT

PREMISES KNOWN AS LOT 528,02 IN BLOCK 22 AS SHOWN ON THE TAX MAP OF THE TOWNSHIP OF NEPTUNE

I HEREBY CERTIFY THAT TO THE BEST OF MY KNOWLEDGE, INFORMATION AND BELIEF, THIS MAP IS A RESULT OF A FIELD SURVEY MADE BY ME, OR UNDER MY DIRECT SUPERVISION, ON AUGUST 15, 2005 IN ACCORDANCE WITH THE RULES AND REGULATIONS PROMULGATED BY THE "STATE BOARD OF PROFESSIONAL ENGINEERS OF THE METHODOT EPROOPS, CHERCH. PREMISES ALSO KNOWN AS A PORTION OF LOT 528 AS SHOWN ON A CERTAIN MAP OF LOTS OF CAMP GROUND OF THE OCEAN GROVE CAMP METING ASSOCIATION

THE INFORMATION SHOWN HEREON CORRECTLY REPRESENTS THE CONDITIONS FOUND AT, AND AS OF THE DATE OF THE FIELD SURVEY, EXCEPT SUCH IMPROVEMENTS OR EASEMENTS, IF ANY, BELOW THE SURFACE AND NOT VISIBLE.

AND LAND SURVEYORS

KATHLEEN A. WILLIAMSON AND SUSAN L. PRESTON, BOTH SINGLE WEICHERT FINANCIAL SERVICES, ITS SUCCESSORS AND/OR ASSIGNS AS THEIR INTERESTS MAY APPEAR

RECENT ASSERAGE THE AGENCY, LL.C.

TRANSMATION TITLE INSURANCE COMPANY

CAUTION: IF THIS DOCUMENT DOES NOT CONTAIN A RAISED IMPRESSION SEAL OF THE PROFESSIONAL, IT IS NOT AN AUTHORIZED ORIGINAL DOCUMENT AND MAY HAVE BEEN ALTERED

PREPAREDBY

MICHAEL J. WILLIAMS LAND SURVEYING L.L.C

56 MAIN AVENUE, OCEAN GROVE, NEW JERSEY 07756 (732) 988-0440

MICHAEL J. WICLIAMS, L.S., N.J., LIC, NO. 25800

SURVEY OF PROPER

25 OLIN STREE

NEW JERGEY MONROUTH COUNTY

BOALE !" = FQ

16 · 83

AUGUST 15, 2005

anniproprocessor de la constanta de la constan	***	33	31655	61389 BURCLAR ALARM/ZS OLIN
a diponina di manana	M 20 K	# 250 M	Ó SE	7 S S
	N .	R	3	**************************************
	5/8.02 20060024 01/11/20	528.D2 20060410 03/35/200	5280Z 20050446 04/17/200 20060446 05/16/200	
300	2006024 01/11/206	20060410 03/31/2006	Z0060486 TANK 0A/17/Z006, HEAT 20060486-A. AIR 05/10/2006 CONI UNIT	04/12/2017
	at one-month on given in divinition and of	SHEETROOK	SOLIN 22 528.02 Z005048 TANK REMOVAL 25 OLINST F 2005045+4, AIR 25/10/2006 CONSTIDNING UNIT	BURGLAR ALARM 29 OLIN ST
AND THE REAL PROPERTY OF THE PARTY OF THE PA	25 OLINST	25 OLINST	250LINST	25 OLIN ST
Serge Comments		<	i.	
	and produced and the second se		× *	\
1.76km and dispensed in second control	No accessory		<	•
NA MANAGEMENT (MANAGEMENT)			<	
	CLOSED	CLOSED	CLOSED	CEOSED
	\$110.00	\$4600	\$299,00	\$250,000 \$10
<	12/25/2005	\$100.00 (03/14/2006	03/24/2006	\$110.00 CX.212.63.14
	0 06/11/2015, 4:31 PM	0 06/11/2015, 4:33 PM	0 06/11/2015. 4/33 PM	832 AM
in attribute and designation accompany	01/11/2006	03/31/2006	94/17/2006	04/12/2017

Print This Page

Construction Project: 31655

NEW INSPECTION CPA Inspection Calendar

is pections										irspections - Pr	Inspections - Project View 1-4 of 4	*
Inspection	Event Subject	Scheduled Date	Assigned To		Result	Approved Date Fall Date #1 Fall Date #	Fall Date #1	Fail Date #2	Workflow Status	Inspection Event Subject Scheduled Date Assigned To Initials Result Approved Date Fail Date #1 Fail Date #2 Workflow Status Workflow Actions	Updated At	Updated By
Electrical												
8	T	05/17/2006		8	Š	Pass 05/18/2006			Passed	To Be Deleted	09/02/2015, 4:27 AM	Tom Vignola
TN N	Ž	05/09/2006		8	I E		05/11/2006	0.000	railed.	Schedule Inspection To 09/02/2015, Be Deleted 4:25 AM		Signola .
7								AND CO.				
쿭	ž	05/09/2006		<u> </u>	Pass	KGN Pass 05/10/2006			Passed	To Be Deleted	09/02/2015, 4:25 AM	S of group
Plumbing											***************************************	
ž	Ē	05/09/2006		RA A	äss	Pass 05/10/2006			Passed	To Be Deleted	09/02/2015, 4:25 AM	Si d'

Copyright © Jungle Lasers Inc. All rights reserved.

Photo 1: Current Location of the Condenser Unit. It is tucked away in a well-protected area and not an impediment or hazard to people moving about the outdoor space.



Photo 2 – View of the condenser unit from the driveway. The unit is fully screened by the fence. The fence we are considering replacing this with would be a simpler board on board picket with no lattice top section. It would continue to fully screen the unit from view from the street.



Photo 3: Alternate placement of the condenser unit. During the Zoom call with Tech Review on January 4, we were told that according to the survey, there appeared to be room to move the condenser to the back side of the bumpout. This photo shows the footprint of the condenser unit (14"wide x 38" long and placed 11" from the side of the house) laid out where it would be placed if we were to move it. The unit it also 31" high, which would place it well above the height of the crawlspace access point.

To access the crawlspace, the plumber has to sit on the ground and lean back, lowering himself feet first into the space. Placing the unit in this space would make is extremely difficult for someone to safely enter and exit the crawlspace.

This placement allows for a few inches of clearance off the corner of the bumpout, which is important for safety as this portion of the yard is used frequently.



