


110 Main Ave. Condition Report: Rear Deck and Fire Escape

4 September 2023


Jenny Shaffer and Kurt Cavano



1890



1905



1930

General comments:

- 110 Main is a key structure.
- The photos, with accompanying descriptions, document the three-story, modern structure at the rear.



- At ground level/first floor, there is a large, open space.
- There was at one point an elevated deck.
- There is what appears to be a patched, new(er) ceiling with a modern light fixture.
- A piece of slate, perhaps part of a set of stairs, is on the ground by the door.



- The second floor of the structure is reached by a set of older stairs.
- The stairs currently are far off the ground.



- The second floor is supported by a square post at the southeast corner.
- The second and third floors abut the house, here on the west side.
- The second floor has a ceiling and light fixture as on the first floor.
- The third floor is open.