

NOTE: This report supplements an earlier site report of 21 November 2022, and concerns only the siding, which now has been largely exposed by the applicant.

GENERAL COMMENTS:

- The distinctive wide clapboard used on the exterior is in varied condition, with about two-thirds in fair to good condition (mostly on the east and west sides) and about a one-third unsalvageable: split boards; lower edge of boards damaged when later layers applied and removed; and water damaged boards (especially towards the south/rear under windows).
- The corners are woven.
- All sills were cut and window headers removed to apply later siding.
- The vinyl fascia remains in place, so it is unknown what is beneath it.
- The clapboard on the lower north/front façade is unsalvageable.
- Unsheathing what was the small, original front porch on the front/north façade revealed the original shadow block foundation; it also revealed that the original porch appears to have had a clapboard half wall, though the clap is unsalvageable.
- The applicant has not yet removed the upper front/north façade sheathing; while we anticipate that the clap beneath will be compromised due to the application of the masonry layer, removal of the applied masonry will aid in determining the original fenestration.

as yet unexposed

vinyl fascia
(goes around entire
house)

damaged clap of half-
wall

shadow block foundation



main/north facade



split/damaged clapboard on “sunroom”/porch and lower north elevation with woven corner



northwest corner



west rear elevation



southeast elevation



window to east rear with water damage below



southeast corner with woven corner



west elevation window with surround extending at top and missing header, cut sill below



another typical window surround