Deborah Osepchuk, Chair Lucinda Heinlein, 1st Vice Chair Leonard J. Steen, 2nd Vice Chair Steven R. Tombalakian, Esq., HPC Attorney Ronald D. Cucchiaro, Esq., HPC Attorney Dawn Crozier, Administrative Officer Kristie Dickert, Secretary



Douglas MacMorris, Member Jeffery Rudell, Member Jenny Shaffer, Member Joseph Wierzbinsky, Member Douglas McKeon, Alternate No. 1 Linda Henderson, Alternate No. 2

OFFICE OF THE HISTORIC PRESERVATION COMMISSION

25 Neptune Boulevard Neptune NJ 07753 (732) 988-5200 x. 204 Fax (732) 988-4259 kdickert@neptunetownship.org

Regular Mail Electronic Mail:

ectronic man.

May 7, 2020

Bahija Cleary 92 Embury Avenue Ocean Grove, NJ 07756

RE: HISTORIC PRESERVATION COMMISSION APPLICATION NO. HPC 2020-060 BLOCK 224 LOT 6 ALSO KNOWN AS 92 EMBURY AVENUE

Dear Applicant:

Please be advised the above mentioned application has been reviewed for completeness and the Application Review Team (Review Team) has determined that this application cannot be administratively approved. Therefore, you are hereby notified that your application has been scheduled for a virtual public hearing before the Historic Preservation Commission. Your application has been scheduled for a virtual public hearing/meeting on <u>Tuesday</u>, <u>June 9</u>, <u>2020 at 7:00 PM</u>. The meeting will be held virtually via Zoom. Log-in and Participant information is as follows:

Topic: Historic Preservation Commission Regular Meeting Time: Jun 9, 2020 07:00 PM Eastern Time (US and Canada)

Join Zoom Meeting

https://us02web.zoom.us/i/83976444365?pwd=TW5WSHFScmNIZmdIZmp0REt0elJyZz09

Meeting ID: 839 7644 4365

Password: 951530 One tap mobile

+16465588656,,83976444365#,,1#,951530# US (New York) +13126266799,,83976444365#,,1#,951530# US (Chicago)

Dial by your location

- +1 646 558 8656 US (New York)
- +1 312 626 6799 US (Chicago)
- +1 301 715 8592 US (Germantown)
- +1 346 248 7799 US (Houston)
- +1 669 900 9128 US (San Jose)
- +1 253 215 8782 US (Tacoma)

Meeting ID: 839 7644 4365

Password: 951530

Find your local number: https://us02web.zoom.us/u/kcBDckNzjf

Preliminary Review Notes

Below please find the Application Review notes. Please understand that this is a preliminary review. It includes, but is not limited to, the observations on the following pages concerning your project. In no event shall this preliminary review constitute an approval. Neither the Applicant nor the Review Team is bound by this review. Also, these comments do not preclude additional information requests, comments, or concerns from the HPC Members before or at a hearing. The Applicant or the Representative of the Applicant should carefully review the notes below and be prepared to discuss these items.

Description of Work

- "1. Replace 27 windows of the house. The windows are mixed. Some of the windows are wood and "very old as it shows in the pictures, and when it rains, the water come in trough [sic] the old rotton [sic] wood". Other windows are vinyl, broken, and cannot open.
- 2. "The new windows will be purchased from "Window Word" a good company that provid [sic] good service." The windows will be white with 6 grids to look like the neighbors to the left side of 92 Embury Avenue."

Classification:

According to the Tax Assessor's Records the subject property was constructed in **1919**. Therefore it is considered a **Contributing Structure** (by date). Contributing Structures include those dwellings originally constructed between the 1910 and 1941 consisting primarily of Colonial Revival, Shingle Style, American Four-Square, Bungalow/Craftsman and other Late Pattern Book Victorian. **Key and contributing structures are most carefully scrutinized during the HPC review process.**

Compliant Items:

1. NONE

Non-Compliant Items/Issues:

- Replacement of Original Wood Windows. According to the Applicant the windows were installed in 1919. The Applicant should be prepared to justify the need for replacement instead of restoration. Please review the following sections of the current Design Guidelines:
 - a. As per Section IV, Subsection E. Windows, Page 17, No. 1. Make every effort to repair and restore all windows and the associated components. If replacement is necessary the replacement should duplicate the original design and be consistent with the time period. In the event duplication is either technically or economically unfeasible, a simplified version will be considered by the HPC when window size and shape is of the same proportion or configuration appropriate to the historic character of the dwelling. Please provide documentation justifying the need for replacement of the windows, instead of repairs and/or restoring.
 - b. **As per Section IV, Subsection E. Windows, Page 17, No. 4.** Preserve or reconstitute window transoms, associated hardware and trim.
- 2. Window Trim. As per the Applicant the window trim is not being replaced but will be painted. The Applicant must provide the proposed paint color for the window trim;
- 3. **Window Style and Material.** The current windows appear to be all wood two-over-two windows. The Applicant is proposing to install all vinyl 6-over-6 windows with true divided lights (TDL). Please review the following section of the current Design Guidelines:
 - a. As per Section IV, Subsection E. Windows, Page 17, No. 5. Retain or replicate the glazing configuration(s) as per the original or otherwise determined to be historically appropriate;
 - b. As per Section IV, Subsection E. Windows, Page 18, No. 6. Windows should be manufactured in wood but could be clad in either metal or vinyl as an Owner's choice. However, wood windows are always preferred.

Additional Information Request:

- 1. The Applicant must provide 11 copies of the submitted color photographs documenting the condition of each window to be replaced and catalog cuts to this office by Friday, May 22, 2020;
- 2. Any additional documentation that may help demonstrate the condition of the windows to be replaced must be submitted to this office by Friday, May 22, 2020.
- 3. No new evidence or exhibits can be submitted during the meeting;
- 4. Additional information about the meeting can be found online at: http://neptunetownship.org/agendas-minutes/historic-preservation-commission once the agenda has been posted.

If any changes are made to your application after you have been placed on the agenda, or if you fail to produce any of the items requested by the Commission, your hearing will be deferred to the next available meeting.

It is highly recommended that you attend this virtual hearing in order to address any questions or concerns the Commission may have. An Architect, Contractor, or Attorney may accompany you, or you may appoint a representative in the event you are unable to attend/participate. Please be advised, your absence or lack of participation in the virtual meeting may cause your application to be deferred.

For your convenience, the Ocean Grove Historic District Guidelines for Residential Structures can be found online at www.neptunetownship.org.

The HPC thanks you for your cooperation and support in maintaining the integrity and character of the Ocean Grove, a registered National and State Historic District. Should you have any further questions or concerns please feel free to contact me at (732) 988-5200, extension 278 or via email kdickert@neptunetownship.org.

Cordially,

Kristie Dickert HPC Secretary



Property Location: 92 EMBURY AVE Application No: HPC2020-060

Application Date: 03/06/2020

DATE APPROVED:

HISTORIC PRESERVATION COMMISSION CERTIFICATE OF APPROPRIATENESS - INCOMPLETE

AC UNIT		GATE	RAILINGS			
ADDITION		GENERATOR	RETAINING WALL			
ARBOR		GUTTERS & LEADERS	ROOF			
AWNING		HOT TUB	SATELLITE	DISH		
BALCONY		LATTICE	SHED			
CHIMNEY		LIGHT FIXTURE	SHUTTERS			
COLUMNS		NEW CONSTRUCTION	SIDING			
DECK		ORNAMENTATION	SIGN			
DOOR REPLACEM	1ENT	OUTDOOR SHOWER	SKYLIGHT			
DRIVEWAY		PAINT	SOLAR			
EXTERIOR ALTERATIONS		PATIO	STAIRS			
FENCE		PIERS	VENT			
FLAGS/BANNERS	FLAGS/BANNERS		WALKWAY			
FOUNDATION	FOUNDATION		WINDOWS :			
OTHER						
Block: 224	Lot: (6	Qualifier:			
OWNER INFORMATIO)N					
Name(s): BAHIJA CLE	ARY					
Address 92 EMBURY A	NE OCEAN GROV	E, NJ 07756				
Phone: (Email:				
APPLICANT INFORMA	ATION	-		1		
Check if same as O	wner					
Names(s): BAHIJA CLE		Company:				
Address: 92 EMBURY		, ,				
Phone:		Email:				
PROPERTY INFORMA	TION		and the state of t	arten aus deutschen Vereine der erstelle deutsche Erstelle der erstelle deutsche Erstelle der Erstelle des Erstelle des		
Property Type?(check of	one)					
Single Family	Multifamily:	0 Units Commercial	Condo	ixed Use		
Architectural Period / Ye	ear Built: <u>1919</u>	Y NYYY PYN SYDD PHINY HY SIN SHAPLI DAWY PRONG PANGALALANA A PY APPARAISH A SIN SIN SIN SIN SIN SIN SIN SANARA	Architectural Style:	THE STATE OF THE PARTY OF THE P		
Demolition hearing requ		10	•			
		rmit prior to applying for a Certifi	cate of Appropriateriess)		
Zoning Permit Acquired	IY - YES 🀔 NO -	N/A				

Zoning Permit ID# (from Zoning Permit)

APPLICATION REVIEW NOTES:

The Review Team has deemed this application incomplete, as the Applicant has not submitted all required information to evaluate the project as described on the application and in the information sheet. The Review Team has identified general and specific deficiencies based on Neptune Township Land Development Ordinances and Ocean Grove Historic District Architectural Design Guidelines. Please understand that this is a preliminary review. It includes, but is not limited to, the observations below:

Description of Work

As per the work described in the application, the Applicant proposes to:

1. Replace 27 windows of the house. The windows are mixed. Some of the windows are wood and "very old as it shows in the pictures, and when it rains, the water come in trough [sic] the old rotton [sic] wood". Other windows are vinyl, broken, and cannot open.

As per Section IV, Subsection E. Windows, Page 17, No. 1. Make every effort to repair and restore all windows and the associated components. If replacement is necessary the replacement should duplicate the original design and be consistent with the time period. In the event duplication is either technically or economically unfeasible, a simplified version will be considered by the HPC when window size and shape is of the same proportion or configuration appropriate to the historic character of the dwelling. Please provide documentation justifying the need for replacement of the windows, instead of repairs and/or restoring.

Applicant must advise the Commission if any of the windows being replaced are original, if so, please be prepared to show the location of each original window and the need for replacement instead of repair and/or restoration. This can be done by taking a photo of the entire elevation of each side of the house and indicating which windows are original as well as which windows are proposed to be replaced. The photos that have been submitted do not indicate which side of the house or location of where the windows in the photo are located. Please also document the age, style, condition, and material of each of the existing windows proposed to be replaced.

As per Section IV, Subsection E. Windows, Page 17, No. 4. Preserve or reconstitute window transoms, associated hardware and trim.

Please advise if the existing trim will remain or be replaced. If being replaced please provide further details such as the material and profile of said trim.

2. "The new windows will be purchased from "Window Word" a good company that provid [sic] good service." The windows will be white with 6 grids to look like the neighbors to the left side of 92 Embury Avenue.

These windows cannot be administratively approved as the current home appears to have some original windows with 2 over 2 (2:2) style and must be inspected. Vinyl windows with interior metal material cannot be administratively approved and would require the review of the full Commission.

As per Section IV, Subsection E. Windows, Page 17, No. 5. Retain or replicate the glazing configuration(s) as per the original or otherwise determined to be historically appropriate.

As per Section IV, Subsection E. Windows, Page 17, No. 7. Avoid clip on muntins, window grilles or grids. True divided light window pane assemblies are preferred. Simulated divided light window pane assemblies are acceptable.

Please advise the Commission if the windows are equipped with Ture Divided Lights (TDL) or Simulated Divided Light (SDL).

Section IV, Subsection E. Windows, Page 17, No. 9. Fabricate all replacement or new windows in historic proportions. Windows should be manufactured in wood but could be clad in either metal or vinyl as an Owner's choice. However, wood windows are always preferred.

Please confirm if the windows are all vinyl or manufactured in wood, cladded in vinyl. Submit a catalog cut that provides these details.

Incomplete Items:

1. A color photo of the entire front of the home must be provided.

Submitting Required Information:

Emailed submissions will not be accepted. The requested information can be submitted to the Commission Secretary, Kristie Dickert, via hand delivery or standard mail. Please include a cover letter stating the reason for the submission or write "Response to Application Review" at the top of all your documents, be sure to also include your application number. The mailing address is as follows:

Kristie Dickert, HPC Secretary Land Use Department 25 Neptune Boulevard Neptune, NJ 07756.

Kristie Dickert, HPC Secretary

Date:

IMPORTANT INFORMATION:

This application will remain incomplete until all requested information has been submitted. Once this office receives the required information, the Applicant Review Team will review your application again. If it is determined that some or all of the proposed work does not demonstrate compliance with the current Ocean Grove Historic District Architectural Design Guidelines for Residential or Commercial Structures, you will be scheduled to appear before the full Historic Preservation Committee.

In accordance with Ordinance No. 16-32 Any person, firm or corporation that shall violate any provisions of this Ordinance shall, upon conviction thereof by any court authorized by law to hear and determine the matter, be fined such sum not exceeding \$2,000.00 as such court in its discretion may impose; or if the parties so convicted be a natural person, such person may be imprisoned for such term not exceeding 90 days as such court in its discretion may impose, or appear at community service not exceeding 90 days or any combination thereof as such court in its discretion may impose. Each day that such violation exists shall constitute a separate offense.

CC:

	Assessmen 224	Prop Loc:	92 EMBUR	RY AVE		Owner:	CLEARY, BAHI	3A	Square Ft:	2475
3lock; _ot:	6	District:		TUNE TOW	NSHIP	Street:	92 EMBURY A		Year Built:	1919
Qual:	O .	Class:	2	, 0112 , 011		City State:	OCEAN GROVI		Style:	5
-Quaii					Add	itional Inform	ation			
Prior Block:	86	Acct Num:	00013560)		Addl Lots:			EPL Code:	0 0 0
Prior Lot:	931	Mtg Acct:				Land Desc:	31X60		Statute:	
Prior Qual:		Bank Code:	0			Bldg Desc:	2.5S-F-L-1U		Initial:	000000 Further: 000000
Jpdated:	03/05/20	Tax Codes:	F02			Class4Cd:	0		Desc:	
Zone:	HDR1	Map Page:	MARSHAN CONTROL CONTRO		TO SERVICE OF THE PARTY OF THE	Acreage:	0		Taxes:	14667.45 / 14577.59
						ale Informatio		0.6		
Sale Date:	02/07/20	Book:	9397 Pag			Price:	500000 NU#	: ZO		
Si1a	THE PERSON NAMED IN COLUMN	Date	200000000000000000000000000000000000000	Page	Price		Ratio		***************************************	rantee
More Info	10/2	1/19	9379	5418	435000	26	158.60	KIRBY, GORI	ON & DONN	4
					T/	AX-LIST-HISTO	DRY			
Year	Owner	Information	l.	and/Imp/To	Evemntin		operty			
ieai	OWITET .	1111011111251011	-				lass			
<u>2020</u> TRURA	N,PHYLLIS A	% DAVID TRU	ran Poa	349000) 0	749600	2			
PO BOX	X 53			400600	}					
HALCO	TTSVILLE, N	Y 12438		749600)					
<u>2019</u> TRURA	N,PHYLLIS A			314000) 0	689900	2			
	UTH MAIN ST	REET #244		375900)					
57 SOL				689900	1					
	NE, NJ 07753	3		003300						
	NE, NJ 07753	3		009500						•
NEPTU	NE, NJ 07753 N,PHYLLIS A			314000		687000	2			
NEPTU 2018 TRURA					0 . 0	687000	2			
NEPTU 2018 TRURA 57 SOI	IN,PHYLLIS A UTH MAIN ST	REET #244		314000	0 .0	687000	2			
NEPTU 2018 TRURA 57 SOI	N,PHYLLIS A	REET #244		314000 373000	0 .0	687000	2			
NEPTU 2018 TRURA 57 SOU NEPTU	IN,PHYLLIS A UTH MAIN ST INE, NJ 07753	REET #244 3		314000 373000) . 0)		2			
NEPTU 2018 TRURA 57 SOU NEPTU 2017 TRURA	IN,PHYLLIS A UTH MAIN ST	REET #244 3		314000 373000 687000	0 .0					

^{*}Click on Underlined Year for Tax List Page

^{*}Click Here for More History



HISTORIC PRESERVATION PHONE 732-988-5200 FAX 732-988-4259

Application #: HPC 2020 - 060

Application Date: 3-4-2020 rec. 4421-cash

Historic Preservation Commission Certificate of Appropriateness Application

☐ AC UNIT	☐ GATE	U RAILINGS
□ ADDITION	☐ GENERATOR	☐ RETAINING WALL
☐ ARBOR	☐ GUTTERS & LEADERS	□ ROOF
☐ AWNING	☐ HOT TUB	☐ SATELLITE DISH
□ BALCONY	☐ LATTICE	☐ SHED
☐ CHIMNEY	□ LIGHT FIXTURE	☐ SHUTTERS
□ COLUMNS	□ NEW CONSTRUCTION	☐ SIDING
□ DECK	□ ORNAMENTATION	☐ SIGN
□ DOOR REPLACEMENT	□ OUTDOOR SHOWER	☐ SKYLIGHT
□ DRIVEWAY	W PAKOK	□ SOLAR
☐ EXTERIOR ALTERATIONS	□ PATIO	☐ STAIRS
☐ FENCE	☐ PIERS	☐ VENT
☐ FLAGS / BANNERS	□ PORCH	☐ WALKWAY
□ FOUNDATION	□ PORCH FAN	₩ WINDOWS
		·
□ OTHER Please complete this application i		
depending on the scope of work pro or any other useful references for re	each application, you are required t	o submit color photos of the property, and, material samples, color samples, catalog cuts, d for a meeting, you may be required to submit uments.
	bury Ave Olean 6	Cove NA 0+156
	LOT: 6	QUALIFIER:
BLOCK: <u>224</u>		
owner information NAME(S): Bahide	Cleacy	
ADDRESS: 92 Embu	ry AVE ocean Grov	e NX 07756
PHONI	EMAIL: _	
APPLICANT INFORMATION		
3 4 .		
Check if same as Owner		
NAME(S):	COMPANY:	
ADDRESS:		
PHONE:	EMAIL:	
APPLICANT CAPACITY – IF OTH		
a Lessee a Agent a Memore		Page 1 of 2

PROPERTY TYPE (Check one):	
▼ Single Family □ Multifamily: Units □ Commercia	al 🗆 Condo 🗀 Mixed Use
ARCHITECTURAL PERIOD / YEAR BUILT: 1919 ARCHITECTURAL PERIOD / YEAR BUILT:	CHITECTURAL STYLE:
Does your project include demolition of 15% or more of extending the second of the sec	erior of existing structure? YES NO ving for a Certificate of Appropriateness.
Do you have Zoning Department approval for this project? ZONING PERMIT ID# (from Zoning Permit): Please Note: If zoning approval is required for the work desincomplete until zoning approval is received. Incomplete approval	DATE APPROVED:scribed on your application, your application will remain
Describe all proposed work to be conducted on subject materials to be used. Attach additional pages if necessary. To Whom it my Collein,	
and very old as it shows in the water comes in trough the old co are vinal and oll broken and a the pew windows will be a good company that provid a the windows will be white written our niebor windows on the let	the pictures, and when it raines, the other window wood, and the other window word unchapsed from Window Word good material and good service in 6 grids so the Can Look like Fit side of 92 Embury are Thank as a fine of 92 Embury are Thank as a fine of 92 Embury are Thank as a fine of 92 Embury are Thank
 Property site visits by Neptune Township Sta project has been deemed to be complete. 	aff, HPC Members and HPC Professionals until the
 The information herein is correct and complete 	
 The HPC or HPC Application Review Team be considered complete. 	may require additional information for your application to
By signing this application, the Owner authorizes the list public hearing before the Commission.	sted Applicant to appear as their representative at a
OWNER-NAME - Please PRINT	APPLICANT NAME - Please PRINT
OWNER SIGNATURE	APPLICANT SIGNATURE
DATE	DATE

Unit type: SINGLE FAMILY

DWELLING



TOT2020-0020

Certificate of Inspection

Township of Neptune
Neptune, New Jersey
CODE ENFORCEMENT DIVISION

For: BAHIJA CLEARY

Address: 92 EMBURY AVE

.....

Unit:

Date: 02/05/2020

Block: 224

Lot: 6

Owner: KIRBY, GORDON & DONNA

92 EMBURY AVE

OCEAN GROVE, NJ 07756

Signature of Code Enforcement Inspector

THIS CERTIFICATE NOT TRANSFERABLE

Inspection Date:

Inspector: Kevin Diaz

Total # of Units: 1

Fee Paid: \$ 65.00

BAHIJA CLEARY 59 KINGSLEY PLACE OCEAN GROVE NJ 07756

emailed.

92 Embury Ave- Window Replacement

Classification:

According to the Tax Assessor's Record's the subject property was constructed in 1919. Therefore it is considered a Contributing Structure (by date). Contributing Structures include those dwellings originally constructed between the 1910 and 1941 consisting primarily of Colonial Revival, Shingle Style, American Four-Square, Bungalow/Craftsman and other Late Pattern Book Victorian. Key and contributing structures are most carefully scrutinized during the HPC review process.

Description of Work:

As per the work described in the application, the Applicant proposes to:

- 1. Replace 27 windows of the house. The windows are mixed. Some of the windows are wood and "very old as it shows in the pictures, and when it rains, the water come in trough [sic] the old rotton [sic] wood". Other windows are vinyl, broken, and cannot open.
- 2. "The new windows will be purchased from "Window Word" a good company that provid [sic] good service." The windows will be white with 6 grids to look like the neighbors to the left side of 92 Embury Avenue.

Dawn's notes:

At the time of submitted I advised the Applicant of the following:

- 1. Not to purchase the window until she gets approval from HPC;
- 2. HPC may request color photographs;
- 3. If the original windows are 2-over-2, if approved, they may require 2-over-2 be installed not 6-over-6 like the neighbors
- 4. She said the windows are wood-core. If the documents do not provide this information, she will need to submit it at a later time.
- 5. Site-visit will be requested

Section from Design Guidelines:

Section IV, Subsection E. Windows, Page 17, No. 1. Make every effort to repair and restore all windows and the associated components. If replacement is necessary the replacement should duplicate the original design and be consistent with the time period. In the event duplication is either technically or economically unfeasible, a simplified version will be considered by the HPC when window size and shape is of the same proportion or configuration appropriate to the historic character of the dwelling. Please provide documentation justifying the need to replacement the windows, instead of repairs and/or restoring. Please contact this office to schedule an on-site visit at least 10 days prior to the scheduled hearing date.


Section IV, Subsection E. Windows, Page 17, No. 4. Preserve or reconstitute window transoms, associated hardware and trim. Please advise if the existing trim will remain or be replaced. If being replaced please provide further details such as the material and profile.


Section IV, Subsection E. Windows, Page 17, No. 5. Retain or replicate the glazing configuration(s) as per the original or otherwise determined to be historically appropriate.

Section IV, Subsection E. Windows, Page 17, No. 7. Avoid clip on muntins, window grilles or grids. True divided light window pane assemblies are preferred. Simulated divided light window pane assemblies are acceptable. Please advise the Commission if the windows are equipped with Ture Divided Lights (TDL) or Simulated Divided Light (SDL).

Section IV, Subsection E. Windows, Page 17, No. 9. Fabricate all replacement or new windows in historic proportions. Windows should be manufactured in wood but could be clad in either metal or vinyl as an


Owner's choice. However, wood windows are always preferred. Please confirm if the windows are all vinyl or manufactured in wood, cladded in vinyl. Submit a catalog cut that provides these details.









https://outlook.live.com/mail/0/inbox/id/AQMkADAwATYwMAltODE5Zi0zZmU3LTAwAi0wMAoARgAAA3zzZDKzwVdMojGrl7KTypgHAloEkyxBzR9MiC...




https://outlook.live.com/mail/0/inbox/id/AQMkADAwATYwMAltODE5Zi0zZmU3LTAwAi0wMAoARgAAA3zzZDKzwVdMojGrl7KTypgHAloEkyxBzR9MiC... 1/2












2 4 0 0 2 0 2 4 2	Outlook	P Search © ♥ P ←
	New message	与 Reply ∨ 圃 Delete 〒 Archive ○ Junk ∨ ≼ Sweep ⑤ Move to ∨ ♥ Categorize ∨ ⑥ Snooz
~	Favorites	Re: Photo Of Double Hung Window With Grids
百	Archive	JC Mon 2/24/2020 2:14 PM ← ← ← ← ← ← ← ← ← ← ← ← ← ← ← ← ← ←
Я	sleeptight@news 8	You ≽
Я	DoNotReply@unit	Dear Bahija,
	Add favorite	The new windows will be fusion welded white vinyl framed, and with stainless steel reinforcement inside. Each and every window is custom made to ensure you get exactly what is needed.
~	Folders	The exterior look of the new windows will match the exterior look of the existing windows in all respects. So the exterior color will match, the size and style will match, and the grid pattern
~	Inbox 7333	will match. (The stainless steel is fully hidden inside the window structure.) We do hundreds of jobs in associations every year and generally they insist that the appearance
	Bahijas Files 5	match the existing windows. So we have a great deal of experience with matching the look.
0	Junk Email 612	The windows come with a full lifetime warranty, which fully covers scal failure and accidental glass breakage. Thank you, Sincerely,
0	Drafts 114	
₽	Sent Items	John, Window World of the Jersey Coast
Û	Deleted Items 2	On February 21, 2020 09:34:45 pm EST, 1
	Archive	Hi, thank you for the picture, but I will need specifics about the windows how they are made and what are they
	Notes	made of. Thank you
	Anna Jakow	Get Outlook for iOS
	Bahija Maha	
	Conversation Hist	
	Morgage	Good afternoon Bahija,
	Notes_0	Please find the attached photo that you requested from Tony. If you have any questions you can reach our office at 732-417-5700. Thank you.
	Photos	
	SAT	Sincerely, Margie DeRogatis Assistant Operations Manager
	New folder	Window World of The Jersey Coast 732-417-5700 Phone 732-417-5757 Fax
~	Groups	
	New group	



I have small kids and Family, these windows are no longer safe, they are all baken, glace is every where and we have that o tape few to keep them in place until we seplace them, we can't fix them, based on there age the wood shifted from side to side, and is very rotten.

1- # glace windows are broken and Loose

4 the windows can't close evenly

at the chaines holding the windows on the

Side are all broken, can't pull them up or down

of the windows are not sufficients

of the cetter wood inside and out.

Cost: 3 times costly then replacment) we can't

2 The windows we are getting to replace the old onse are the same size as the one we have now the The new windows are equiped with The divided lights (TDL), the are double hand 50/50 exactly as the are right now.

A yes they are TDL windows.

A jes vieg the IDL willadows.

3- I attached all the colored pictures purasked For.

4. All the wood windows were installed in
1919 Since the house was built

5. the house has attend already vingl windows

7 windows on the First floor all boken
and cheaply made can't close or open.

6. The trims inside and sut will not be
replaced but painted

4 The windows "the new ones" are
equiped with ture devided lights

(TDL)

4 The new windows are doublehand

50/50 exactly as they are right now

we will appreciate your help.
Thank you
Bahija cleary

Bahija Cleary 4/29/22 To whom it my Green,

1- I cercled the pictures and wrote a number on it one of them to matchait with the one than needs to be replaced from inside 2- the company will send a letter specifying about TDL or SDL

3 - Window are Vinyl.

Thankysen



* W. 3500 Series

* Customizable in 1/8" increments

* Higher grade Low E insolation
glace

* Energy-efficient Energy star

& Great for historical renovations




The exquisite design of Window World Double-Hung Windows is the perfect choice for those who want a beautiful, classic appearance. Functional beauty, easy maintenance, energy efficiency, and a wide selection of decorative options will help personalize your environment.

Masterfully crafted with attention to every detail, Window World Windows are available in a full selection of styles to let you design the ideal window system for your home.



ENERGY STAR U.S. Climate Zones



Window World offers a variety of ENERGY STAR qualified glass packages specifically tailored to your climate zone.

The Following Features are Standard on all Window World **Double-Hung Windows*:**

- Vinyl frame and sashes are made tough and solid with a uPVC compound that will never chip, peel, crack, or warp.
- Multi-chambered sash and mainframe provide superior thermal efficiency.
- Warm-Edge Spacer System maximizes performance and longevity.
- Interlock at sash meeting rails creates a super-tight seal against air infiltration while adding security.
- Drop-in glazing for extra protection from the elements.

Plus These Additional Features:

- Dual vent stops for controlled ventilation and airflow.
- Full balance covers help protect against air infiltration while adding a finished appearance.
- · Constant force balance system eliminates sash cords, weights, and pulleys. You'll benefit from smooth, comfortable fingertip operation.
- Tilt-in top and bottom sashes make cleaning safe and easy from inside the home.

Enhance Your Windows with These Options:

- SolarZone Insulated Glass Packages featuring Low-E glass and a Warm-Edge Spacer System for enhanced insulating performance.
- Full or half fiberglass screens provide ventilation while keeping insects out.
- Standard and contoured grids are placed between the panes for easy cleaning

All Window World Windows are manufactured to stringent ENERGY STAR requirements and testing guidelines set forth by the National Fenestration Rating Council (NFRC).




The National Fenestration Rating Council establishes test criteria that set the standard for performance ratings of window and door products. These consistent ratings

provide accurate information on the energy performance of windows, doors, and skylights.




ENERGY STAR is a joint program between the U.S. Department of Energy (U.S. DOE) and the U.S. Environmental Protection


Agency (EPA). It assists consumers in recognizing energy-efficient products and promoting the environmental and economic benefits of these products through labeling and other activities.




Back of the House can't close or open is inside # 14









Front House Second Floor bedroom

window, can't open

or close broken

metal & cord.