

HISTORIC PRESERVATION PHONE 732-988-5200 .x. 236 FAX 732-988-6433

Application #: HPC 2021-215

Application Date: 12/9/21

Historic Preservation Commission Certificate of Appropriateness Application

AC UNIT	☐ GATE		RAILINGS
ADDITION	☐ GENER	ATOR	☐ RETAINING WALL
☐ ARBOR	☐ GUTTE	RS & LEADERS	■ ROOF
☐ AWNING	☐ HOT T		☐ SATELLITE DISH
☐ BALCONY	■ LATTIC		SHED
☐ CHIMNEY	🗅 LIGHT		SHUTTERS
■ COLUMNS	;	ONSTRUCTION	● SIDING
□ DECK	1	MENTATION	☐ SIGN
■ DOOR REPLACEMENT	\$	OOR SHOWER	☐ SKYLIGHT
DRIVEWAY	□ PAINT	•	SOLAR
EXTERIOR ALTERATIONS	□ PATIO		■ STAIRS
D FENCE	☐ PIERS	•	□ VENT □ WALKWAY
☐ FLAGS / BANNERS	● PORCH		■ WINDOWS
☐ FOUNDATION	. □ PORCH	IFAN	• WINDOWS
□ OTHER			
Guidelines are available online at value on the complete applications will not REQUIRED INFORMATION: With the pending on the scope of work parts.	vww.neptunetown be accepted. h each application oposed, architect eview. Once your	ship.org. Please type on, you are required a ural plans or sketches, application is schedule	to submit color photos of the property, and, material samples, color samples, catalog cuts, ed for a meeting, you may be required to submit
PROPERTY IDENTIFICATION -	your application a	The Other Capititicoa doc	
ADDRESS: 17 Webb Avenu	e		
BLOCK: 288	LOT: <u>13</u>		QUALIFIER: HD-O
OWNER INFORMATION			
NAME(S): Ivan Barkhorn	Occan Crave	N I 07756	
ADDRESS: 87 Heck Avenue,			· · · · · · · · · · · · · · · · · · ·
PHONE: <u>732-774-6900</u>		EMAIL: abf@shore	epointarch.com
APPLICANT INFORMATION —			
☐ Check if same as Owner			
	:	COMPANY: ch	ore Point Architecture
NAME(S): <u>Andrea Fitzpatrick, AIA</u>			ore Point Architecture
ADDRESS: 108 S Main St. Ocea	n Grove, NJ 0775	6	
PHONE: <u>732-774-6900</u>		EMAIL: abf@shorepo	intarch.com
APPLICANT CAPACITY – IF OT	HER THAN OW	NER (Check one):	
☐ Lessee ☐ Agent ■ Architect	☐ Contractor	☐ Attorney ☐ Other	
IPC APPLICATION (Revised November 2020)			Page 1 of 2

PROPERTY TYPE (Check one):	
■ Single Family □ Multifamily: Units □ Comme	rcial 🗆 Condo 🗅 Mixed Use
ARCHITECTURAL PERIOD / YEAR BUILT: 1889	
Does your project include demolition of 15% or more of each of YES: you must apply for a Demolition Permit prior to apply for a Demolit	
Do you have Zoning Department approval for this project ZONING PERMIT ID# (from Zoning Permit): 556432747 Please Note: If Zoning approval is required for the work incomplete until Zoning approval is received. Incomplete Describe all proposed work to be conducted on subjections.	DATE APPROVED: 11/30/21 described on your application, your application will remain applications will not be accepted.
materials to be used. Attach additional pages if necessar	y.
(PLEASE	SEE ATTACHED)
	į į
By signing this application, the Applicant and Owner	agree to the following:
 Property site visits by Neptune Township project has been deemed to be complete. 	Staff, HPC Members and HPC Professionals until the
 The information herein is correct and com 	
 The HPC or HPC Application Review Tea be considered complete. 	m may require additional information for your application to
By signing this application, the Owner authorizes the public hearing before the Commission.	listed Applicant to appear as their representative at a
WAN BARKHORN	Andrea Fitzpatrick, AIA - Shore Point Architecture
OWNER NAME - Please PRINT	APPLICANT NAME - Please PRINT
Bhllu	Uht patien
OWNER SIGNATURE	APPLICANT SIGNATURE
12/6/21	12/6/21
DATE	DATE




17 Webb Avenue HPC CoA Application Text

Date	Revision / Submission
12/9/21	HPC Submission (Initial Release)

HISTORY OF SITE

According to the tax records, 17 Webb Avenue was constructed in 1889. The Sanborn maps appear to support this construction date, however the house was expanded and the form was modified numerous times, to date. The Sanborn maps depict the evolution of this structure, with the final diagram representing the existing site conditions.



BIRDS-EYE VIEWS OF EXISTING HOUSE, COLOR CODED TO DEPICT AGE OF ADDITIONS



Birdseye from south-east



Birdseye from east

LEGEND:


Portions of Building that likely existed on 1890

Sanborn



Portions of Building that likely existed on 1930 Sanborn

108 South Main Street Ocean Grove, NJ 07756 P: 732. 774.6900 F: 732.774.7250



HOUSE STYLE:

Due to the large number of additions and due to the fact that the entire structure has been covered in vinyl siding / covered in aluminum coil stock, it is difficult to identify a specific style for this house, therefore our classification is "eclectic". The red (1905) areas appear to have a gothic influence (steeply pitched 14:12 gable roof, "L" shaped plan). The purple areas (1905-1930) appear to have an Italianate influence with a large pent roof at the porch level (possibly added at this time) and a three-story hiproof turret on the east elevation. The green (newer) additions include the enclosing of a portion of an open two-story porch and a rear addition with a non-uniform flat roof configuration.

PHOTOS OF EXISTING CONDITIONS:





FRONT



SOUTH-EAST



EAST SOUTH-WEST





NORTH-EAST EASTSIDE YARD AREA







CLOSE UP OF DETERIORATED COLUMN BASE

OUTLINE OF PROPOSED WORK:

1. Addition / Alterations:

Remove the roof of the existing (newer) two-story portion at the rear of the structure. Infill the open air first floor "alcove" with a one-story addition. Expand the first and second floor at the rear to align with the east face of the existing second floor cantilever projection. Construct a new 4:12 hip roof above this expanded rear two-story area. The new roof to contain an alcove in the center for an AC condenser (will not be visible from the street) to allow for the relocation of an existing AC condenser that is currently positioned in the east side yard (street facing) but is concealed from street view by a six-foot height vinyl stockade fence (to be removed).

Construct a new one-story addition on the east side of the house that includes a covered entry to a side door.

2. Siding replacement, exterior trim replacement, other exterior upgrades:

In 1992, the existing house was approved for installation of vinyl siding over (what the applicant documented as) 5" exposure wood clapboard. Small sections of the vinyl were recently lifted and various exposures of 4" and 4-1/2" were found. As part of this application, we propose the removal of all existing siding layers and replacement with new Hardie Plank clapboard siding, smooth finish, 4-1/2" exposure. We understand the HPC will require a site visit to arrange for the observation of original wood clapboard in select areas and we will schedule this at the appropriate time.

After removing select areas of aluminum coil stock from existing windows, it was determined that the existing window casings contain 4-1/2" (actual) width legs. We propose removal and replacement of all existing window and door casings and replacement with new CPVC trim components to match the existing profile sizes (4-1/2"). Additionally, new CPVC corner boards, fascias, rakes, and other trim components are proposed as indicated.

Gutters: Includes removal of existing "k-style" gutters and replacement with new prefinished aluminum half-round gutters and round leaders.

Roofing: Removal and replacement of existing roof shingles with new "Timberline" asphalt roof shingles.

3. Window and Door Replacements/Removal:

Please refer to the included "Window Catalog" for a detailed outline of the existing windows and doors and the modifications proposed.

4. Porch upgrades:

At first floor front (wrap around) porch, we propose to remove and replace the existing round fluted columns. The corner column was replaced in 2014 by Ocean Grove hardware with a new Permacast fluted column to match the historic design. All other columns are wood (possibly) original and are in poor condition (see photo above). The existing porch pent roof is in poor

condition and will be repaired / restored. New 16"x8" decorative foundation vents will be installed in the (currently) fully enclosed masonry porch foundation wall, as there is limited airflow below the porch flooring. New T&G mahogany porch flooring is proposed as the existing flooring has buckled due to the lack of airflow mentioned above. The existing brick stair on south elevation is to be replaced with new wood framed stair with mahogany treads and CPVC risers and trim. Existing wood railings are in very poor condition and we propose to relace them with a new custom wood railing system, 30" height, with 5" sq. CPVC "Versatex" newel wraps, where indicated.

Existing second and third floor porches to receive new "Intex" 36" height railings, as indicated; new fiberglass decking; new trim; new CPVC beadboard ceilings (2nd floor); new 5" square CPVC "Versatex" newel wraps.

5. Site Improvements

Removal and replacement of concrete walkway on east side of house, as indicated. Removal of vinyl stockade fence along Beach Avenue, as mentioned above. Removal and relocation of AC condenser from east side yard (along Beach Ave.) to roof at rear. Demolish existing outdoor shower on east side, facing Beach Avenue.

6. Other


Construct new gable roof dormer on third floor, east elevation, to allow for the headroom required for the installation of a new door to access the existing uncovered third floor balcony.

Block: Lot: Qual:	228 13	Prop Loc: District: Class:	17 WE	BB AVE NEPTUNE	TOWNSHIP	Owner: Street: City State:	1542 HI	RKHORN REVOCABLE TRUST GH STREET R, CO 80304	Square Ft: Year Built: Style:	
	:: 680 al: : 03/16/22	Acct Num: Mtg Acct: Bank Code: Tax Codes:	: 0	650		Additional Addl Lots: Land Desc: Bldg Desc: Class4Cd:	: 30X52 3SF 0	on	EPL Code: Statute: Initial: Desc:	000000 Further: 000000
Zone:	HD-O	Map Page:				Acreage: Sale Info	0 ormation		Taxes:	16109.22 / 0.00
Sale Dat	e: 02/23/22	Book:	9582 F	Page: 371	2	Price:	1 NU#:	25		
More Inf	<u>fo</u> 11/01		Book 558	Page 1275	Price 920000		Ratio 34.30	BARKHORN, IVAN	Grantee	
More Inf	<u>fo</u> 02/23	3/22 9	582	3712	1)	IVAN BARKHORN REVOCABLE	TRUST	
	operty Location 17 WEBB AVE	433 372	/Tot Ex 3600 2100 5700	emption <i>i</i>	Assessed Pr 805700	TAX-LIST- operty Clas: 2				
2021	17 WEBB AVE	286	9500 5100 5600	0	775600	2				
2020	17 WEBB AVE	271	9500 .100 9600	0	760600	2				
<u>2019</u>	17 WEBB AVE	254	9500 1400 8900	0	663900	2				

New Search Assessment Postcard Property Card

^{*}Click on Underlined Year for Tax List Page

^{*}Click Here for More History



TOTAL AREA = 1,073 SQ. FT.

DEMO AREA = O SQ. FT.

TOTAL AREA = 1,073 SQ. FT.

DEMO AREA = 0 SQ. FT.

TOTAL AREA = 692 SQ. FT.

DEMO AREA = 0 SQ. FT.

TOTAL AREA = 1,119 SQ. FT.

DEMO AREA = 242 SQ. FT.

TOTAL AREA = 1,074 SQ. FT.

DEMO AREA = 333 SQ. FT.

PROPOSED ADDITION/ALTERATIONS:

BARKHORN RESIDENCE

17 Webb Avenue Ocean Grove, NJ 07756 Block: 228 Lot: 13

PROJECT INFORMATION

BUILDING CODES:

REHABILITATION SUBCODE (NJAC 5:23-6)

INTERNATIONAL RESIDENTIAL CODE - 2018 (NJ EDITION), WHERE APPLICABLE

BUILDING STATISTICS:

USE GROUP:

CONSTRUCTION CLASS: NUMBER OF STORIES:

WIND SPEED (Vult): 125 MPH (NOTE: THIS PROJECT IS NOT LOCATED IN A WINDBORNE DEBRIS REGION AS THE VUIL DOES NOT EXCEED 130 MPH

FLOOD HAZARD DATA: THIS PROJECT IS NOT LOCATED IN A FLOOD HAZARD AREA

BUILDING AREA:

	EXISTING	ADDED	TOTAL
FIRST FLOOR AREA	840 SQ. FT.	83 SQ. FT.	923 SQ. FT.
SECOND FLOOR AREA	1,005 SQ. FT.	26 SQ. FT.	1,031 SQ. FT.
THIRD FLOOR AREA	551 SQ. FT.	0 SQ. FT.	551 SQ. FT.
TOTAL HABITABLE AREA	2,396 SQ. FT.	124 SQ. FT.	2,520 SQ. FT.
CONSTRUCTION VOLUME	23,772 CU. FT.	2,348 CU. FT.	26,120 CU. FT.

ZONING INFORMATION

		REQ'D/ ALL <i>O</i> WED	EXISTING	PROPOSED
	MINIMUM LOT AREA	1,800 SQ. FT.	2,327 SQ. FT.	2,327 SQ. FT.
	MINIMUM LOT WIDTH	30 FT.	3 <i>0.</i> 23 FT.	3 <i>0.</i> 23 FT.
	MINIMUM LOT FRONTAGE	30 FT.	3 <i>0.</i> 28 FT.	3 <i>0.</i> 28 FT.
	MINIMUM LOT DEPTH	60 FT.	76.98 FT.	76.98 FT.
#	MIN. FRONT YARD SETBACK BUILDING SETBACK (AVG.):	6.15 FT.	3.52 FT.	3.52 FT.
	PORCH SETBACK (AVG.):	0.44 FT.	2.46 FT.	2.46 FT.
	MIN. SIDE YARD SETBACK- EAST:			
	BUILDING.	2 FT.	2.31 FT.	2.37 FT.
#	PROJECTIONS (INCL. GUTTERS):	2 FT.	0.36 FT.	0.36 FT.
+	WEST: BUILDING,	2 FT.	1.22 FT.	1.22 FT.
#	PROJECTIONS (INCL. GUTTERS):	2 FT.	0.28 FT. OVER	0.28 FT. OVER
+	MIN. COMBINED SIDE YARD SETBACK-	4 FT.	3.59 FT.	3.59 FT.
#	REAR YARD SETBACK	3.1 FT.	1.30 FT.	1.30 FT.
+	PROJECTIONS	2 FT.	0.43 FT.	<i>0.</i> 43 FT.
'	MAX. % BLDG. COVERAGE	85%	53.9%	52.0%
	MAX. % TOTAL LOT COV.	90%	68.6%	65.6%
#	MAX. NUMBER OF STORIES	2.5	3	3
	MAX. BUILDING HEIGHT (M.P.)	35 FT.	28.3 FT.	28.3 FT.
	EXISTING USE OR USES	SING	LE-FAMILY RESIDENTIA	AL
	PROPOSED USE OR USES	SING	_E-FAMILY RESIDENTIA	<u></u>

EXISTING NON-CONFORMITY, UNCHANGED

DRAWING INDEX

- A-I PROJECT INFORMATION, SITE PLAN, DEMOLITION CALCS
- A-2 EXISTING CONDITIONS
- A-3 FLOOR PLANS
- A-4 ELEVATIONS

JOB NUMBER 2021-22

11/22/2021

SIDI

BARKHORN




SIDENCE

BARKHORN

DATE 11/22/2021

JOB NUMBER 2021-22

A-2 BARKHORN



DATE 11/22/2021

JOB NUMBER 2021-22

BARKHORN



Block: 228 17 Webb Avenue

Stephen J. Carlidge, Al/

SHOPE POLY IN THE TOWN NEW Jersey 07756 P: 732.774.6900 F: 732.774.7250 www. shorepointarch.com

ELEVATIONS

ALE: AS SHOWN DRAWN: AB

DATE REVISION/SUBMISSION

11/22/21 ZONING SUB.—INITIAL RELEASE

03/31/22 R1—HPC REVISIONS

TYPE

11/22/21 TONING SUB.—INITIAL RELEASE

11/22/21 TO

JOB NUMBER 2021-22

A-4
BARKHORN



Cut-sheets for HPC CoA Application

SPA Project #: 2021-22 Barkhorn (17 Webb)

Date	Revision / Submission
12/9/21	HPC Submission (Initial Release)

Front Door:



Side Doors:



Asphalt Shingles:





Timberline® HDZ™ Shingles

The look people know and love, now featuring LayerLock™ Technology





Showing products available near 07712 CHANGE >

★★★★ 4.8 (15182) WRITE A REVIEW

FIND A CONTRACTOR

Siding:





ABOUT JAMES HARDIE

Siding | Trim

PRODUCTS

COLOR



Round **PERMA**Cast® Columns

ROUND PERMACAST® COLUMN DIMENSIONS (IN INCHES)*

-11	COL. SIZE	A	В	С	D	Е	F	G	J	К	L	0	N	R	Т	LENGTHS AVAIL (ft.)
	6"	5%"	4%"	9"	1%"	1%"	%"	×"	1%"	1%"	8"	1"	6%"	3%"	4%*	4,6,8
	8"	7%°	6%"	10%"	1%"	1%*	%"	%"	1%*	1%"	9%"	5/2"	2%"	4%"	4%*	5,6880
	10"	9%"	8%"	13%"	2%"	2%"	%"	%"	1%"	1%"	11%"	%"	2%"	5%"	5"	6.0000
	12*	11%*	9%"	16%"	2%"	2%*	%"	1%"	1%*	2%*	13%"	Ж*	2%"	6%"	5%*	6.00 MB
	14"	13%"	11%"	19%"	3%"	3%*	1%"	%"	2"	2%*	17*	%*	2%"	7%"	7"	9,00,00 16,18
ſ	16"	15%*	13%"	22%"	4"	3½"	1%"	1"	2¼"	3"	19%"	1"	3"	8%"	8"	18, 20
	18*	17%*	15%"	24%"	4*	4"	1%"	1%"	2%*	3%"	22%"	1%*	10%*	9%"	8%*	10,12,14,16,18 20,22,24,26
	20"	19%"	17%/	27"	4%"	4%"	2"	1%"	2%"	3%"	241%"	1½"	10%"	11%"	9"	10,12,14,16,18 20,22,24
	22*	21%*	19%"	30%"	5%"	4%*	2"	1%"	3"	3%"	27%"	1%*	10%"	12%"	10%"	16,18,20,22, 24,26
	24"	23%*	21%"	33%"	5%"	5%*	2%;*	2%/	3½"	4%*	30%"	1%*	10%"	13%*	11%"	12,14,16,18,20, 22,24,26,28,30
	28"	28"	24%"	38"	6%"	6"	2%"	2%"	3%"	4%"	33%"	1%*	10%"	15%"	11%"	20,22,24,26,28
	30"	29%*	26%"	41%"	6%"	5%*	2½"	3%;"	4"	4%*	38%"	1%*	10%"	14%"	14%"	20,22,24,26,28 30

^{*}There may be a variance of up to 1/4" in all dimensions. Fluted columns available in all diameters. See page 14 for Parallel dimensions. See page 16 for Ornamental Capital dimensions.

Standard Fluted Column (Fluted in mold)

COLUMN-LOC™

Column-Loc™ creates a continuous connection from floor to beam/ header without the expense of splitting and reattaching the column. This labor saving product is easy to install and delivers wind uplift resistance especially important in coastal

and high wind areas. Currently available for 8 and 10" round (tapered and no-taper) and square PermaCast* columns. Kits are available with and without threaded rod.



ROUND PERMACAST® INSIDE

DIMENSIONS
Inside dimension may vary up to 1/8". Splitting a column will decrease inside dimension 1/8".


COLUMN SIZE	TOP I.D.	BOT I.D.
6"	3%*	4%*
8"	5½"	6%"
10*	7%*	8%*
12*	8%"	10%"
14*	10%"	12%"
16"	12%"	15"
18*	14%"	16%"
20"	16%*	19"
22"	18%"	20%"
24"	20%*	22%"
28"	22"	26%"
30"	25%"	28%"

Plumb-Fit®

To make installation even easier our 6-12" round and square poly Tuscan Cap and Base Sets with flashing cap now come with the Plumb-Fit* installation system included.

SPLIT COLUMN ASSEMBLY KITS (FLANGE KIT)

HB&G offers a split column assembly kit that utilizes a mechanical fastening system for easy and secure assembly. This kit can be purchased separately when ordering a factory split column or they can be ordered pre-installed on factory split columns. This kit is available on select sizes.



Poly Tuscan Base Fluted Column

Aeratis Traditions




Aeratis Traditions tongue and groove porch flooring/ porch decking is a paint ready alternative to inferior wood products like pine, fir and mahogany. Competitively priced at the time of install. Aeratis Traditions T&G porch flooring offers an unsurpassed warranty. endless design capabilities, significantly lower maintenance than wood and an appearance that not even the most discerning historic official could tell it is not a wood porch when your project is complete.

Simply said, "Only a rich man can afford to install a wood porch floor today". This saying has a lot of truth. Not only is the life cycle of pine and fir significantly shorter than it was in years past, many consumers forget the actual annual cost of maintenance. On average many porch owners pay between \$4-\$9 per square foot annually on maintenance and upkeep.

Aeratis Traditions is an uncolored, paint-ready board that is designed specifically to replace wood tongue and groove products. Traditions can be painted or stained in any color. Unlike the Classic or Heritage line which can also be painted, Traditions flooring requires paint or stain to maintain the warranty.

Aeratis Traditions T&G Porch Flooring Dimensions



Lengths: 10', 12', or 16' Width: 3-1/8" (3.092) Thickness: 7/8"



Aeratis Traditions 5-A Paint Adhesion

When painted, Aeratis Traditions maintains a 5-A paint adhesion, the strongest paint adhesion in the industry (no priming needed). This means that you can enjoy the same low maintenance porch that matches the look and feel of your home, ig. a color that exists for your with a 20, year warranty. Most Traditions nor has will hold nain

Once Aeratis is painted, it is hard to tell it is not an authentic wood porch. We engineered Traditions to be used on new and historic homes without being able to tell it is not a real wood porch. Review the two porch floors below. See if you can tell which porch has a wood floor and which porch has a Traditions porch floor. Take into consideration, both porch floors are on historic homes and both were 3 years old at the time of the photo.

Compare the two porches side by side and decide how you would like your painted porch to look after 3 years. The best benefit of Aeratis Traditions is, it is competitively priced to wood at the time of install. On top of a competitive price, you get the paint for FREE (see paint rebate under resources on the right-hand side of this page) and a 20-year warranty.



A 3 year comparison of wood (top) and Aeratis Traditions (bottom).





TILT-WASH DOUBLE-HUNG WINDOWS

Andersen® 400 Series tilt-wash double-hung windows are engineered to provide outstanding performance and style. Combined with the tilt-to-clean sash, it's easy to see why it's our best selling double-hung. Exteriors use three different levels of protection from the elements. On the inside you have the choice of natural pine or low-maintenance white, dark bronze or black' finish. For added style there is a wide range of grille patterns and hardware options.

DURABLE

- · Virtually maintenance-free
- Perma-Shield® exteriors never need painting and won't peel, blister, flake or corrode"
- Frame exterior is protected by a tough vinyl cover that resists dents and repels water and provides long-lasting protection
- · Available with Stormwatch® protection for coastal areas

ENERGY EFFICIENT

- Weather-resistant construction for greater comfort and energy efficiency
- ASK ABOUT ENERGY STAR
- Weatherstripping is designed to seal out drafts, wind and water
- Variety of Low-E4® glass options are available to help control heating and cooling costs in any climate
- Many 400 Series tilt-wash double-hung windows have options that make them ENERGY STAR® v. 6.0 certified throughout the U.S.

BEAUTIFUL

- · Seven exterior color options
- . Natural pine, white, dark bronze or black' interiors
- · Add style with grilles, exterior trim or patterned glass

EXTERIOR COLORS



*Dark Bronze and Black interiors are only available with Dark Bronze and Black exteriors respectively.

See your Andersen dealer for availability. **Visit andersemmindows.com/warranty for details.

"ENERGY STAR" is a registered trademark of the U.S. Environmental Protection Agency.







AWNING WINDOWS

Built on the same platform as our legendary casement window, 400 Series awning windows deliver the same performance and beauty. Their solid wood frames and sash provide strength, while the vinyl covering and weather-tight construction keep the window and your home protected from the elements. On the inside you have the choice of natural pine or a low-maintenance white, dark bronze or black* finish. For added style there is a wide range of grille, hardware and art glass options.

DURABLE

- · Virtually maintenance-free
- Perma-Shield® exteriors never need painting and won't peel, blister, flake or corrode**
- Frame exterior is protected by a tough vinyl cover that resists dents and repels water and provides long-lasting protection
- · Available with Stormwatch® protection for coastal areas

ENERGY EFFICIENT

- Weather-resistant construction for greater comfort and energy efficiency
- ASK ABOUT ENERGY STAF
- Weatherstripping is designed to seal out drafts, wind and water
- Variety of Low-E4® glass options are available to help control heating and cooling costs in any climate
- Many 400 Series awning windows have options that makes them ENERGY STAR® v. 6.0 certified throughout the U.S.

BEAUTIFUL

- · Seven exterior color options
- . Natural pine, white, dark bronze or black' interiors
- · Extensive hardware selection
- · Add style with grilles, exterior trim, art glass or patterned glass

EXTERIOR COLORS





*Dark Bronze and Black interiors are only available with Dark Bronze and Black exteriors respectively.

See your Andersen dealer for availability. **Visit andersenwindows.com/warranty for details.

ENERGY STAR is a registered trademark of the U.S. Environmental Protection Agency.

Newel Posts:



VERSAWRAP

EXPERIENCE THE VERSAWRAP

At VERSATEX, we pride ourselves on coming up with innovative ways to make the builders' lives easier during installation. When we were asked to make covering wood posts more efficient with still improving aesthetics, we delivered the VERSAWIRAD.

The unique design of VERSAWRAP features a product cut with pre-mitered grooves and friction fit joints. The joints are inter-locking with a unique design to allow for easy alignment and additional surface area for bonding.

SAVE TIME & MONEY

Now, instead of cutting four individual joints or miters in the field, you can wrap smarter

with VERSAWRAP column wraps. No more field cutting and struggling to match seams. The VERSAWRAP line includes Classic and Raised Panel designs as a one-piece wrap with accessory options, and a four-piece Tapered design that includes Craftsman-style accessories.

GO BEYOND...

Our Classic and Raised Panel styles are created from a single place of VERSATEX cellular PVC with three pre-mittered grooves that fold around the structural post and lock together with a friction-fit mitter lock joint. Just apply your PVC glue, fold the VERSAWNEAP around your structural column, secure in place, peel the tape, and walk away.

CLASSIC

Nominal Sizes	Actual Inside Dimension	Actual Outside Dimension
4" X 4" X 8'6"	3 3/4" X 3 3/4" X 8'6"	4 3/4" X 4 3/4" X 8'6"
4" X 4" X 10'	3 3/4" X 3 3/4" X 10'	4 3/4" X 4 3/4" X 10"
6" X 6" X 8'6"	5 3/4" X 5 3/4" X 8'6"	6 3/4" X 6 3/4" X 8'6"
6" X 6" X 10"	5 3/4" X 5 3/4" X 10"	6 3/4" X 6 3/4" X 10"
8" X 8" X 8'6"	8 1/2" X 8 1/2" X 8'6"	9 1/2" X 9 1/2" X 8'6"
8" X 8" X 10'	8 1/2" X 8 1/2" X 10'	9 1/2" X 9 1/2" X 10"
12" X 12" X 12"	9 3/4" X 9 3/4" X 12"	11 1/4" X 11 1/4" X 12'

 All 4", 6", and 8" VERSAWRAPs are made from actual ¹/₂" thick VERSATE 12" wraps are made from actual ³/₄" thick material.

RAISED PANEL

Nominal Sizes	Actual Inside Dimension	Actual Outside Dimension
6" X 6" X 8'6"	5 3/4" X 5 3/4" X 8'6"	6 3/4" X 6 3/4" X 8'6"
6" X 6" X 10'	5 3/4" X 5 3/4" X 10"	6 3/4" X 6 3/4" X 10"
8" X 8" X 8'6"	8 1/2" X 8 1/2" X 8'6"	9 1/2" X 9 1/2" X 8'6"
8" X 8" X 10"	8 1/2" X 8 1/2" X 10"	9 1/2" X 9 1/2" X 10"
	A C C C C C C C C C C C C C C C C C C C	

Panels start 16 1/2" from bottom with railing gap from 30 3/4" to 38 1/2". Clearance above the top panel measures 8 3/4".
 For best aesthetic results, painting is recommended to prevent dirt accumulat where panel is milled into product.

versatex.com | 724.857.1111



CPVC Trim:

THE VALUE OF AZEK® PREMIUM TRIM

AZEK Trim provides long-term value through trusted durability and beautiful flexibility. Unlike wood, AZEK Trim doesn't need paint or stain for protection. Our trim comes in a beautiful semimatte white and has exceptional resistance to moisture, no matter the climate. Leave constant maintenance behind. Creatively curve and easily shape AZEK Trim through heat moulding. Set truly premium value backed by our industry-best <u>Lifetime</u> Limited Warranty.

AZEK TRIM FINISHES AND OPTIONS

AZEK offers a wide variety of trim board sizes and options to provide installers, builders and architects the perfect solution for any project or jobsite. All our trim options are made from rot-resistant engineered polymer and are backed by a lifetime limited warranty.

• Moisture-resistant

AZEK boards are 100% protected, inside and out, from both water exposure and absorption.

• Unprecedented durability

Flexible and durable cellular PVC prevents jobsite breakage and delivers long-lasting protection for homeowners.

• Rot-resistant

Say goodbye to splitting, splintering, and rotting caused by consistent exposure to the elements.





Trim Boards —

> AZEK CLASSIC TRIM

- > AZEK TRIM WITH PAINTPRO® TECHNOLOGY
- ➤ AZEK RABBETED TRIM
- > FLANGE SLOTTED WINDOW TRIM

108 South Main Street Ocean Grove, NJ 07756 P: 732.774.6900 F: 732.774.7250

ABOUT

PRODUCTS

QUICK QUOTE

RESOURCES



Dartmouth

Elegant Profile with Modern Characteristics

Our new RS35 Dartmouth Extruded Rail System offers outstanding strength in a range of beautiful, standard designs – available for level and stair rail.



- Improved Matte Finish Matches Our Liberty & Hampton Rails
- > 100% Extruded Cellular PVC with Aluminum
 Core
- > New RS35350 Beverage Friendly Flat Cap
- > 3 5/8" and 4" Rail Widths
- Commercially Code Approved for 12' Span 12'
 Spans contain heavy-duty aluminum
- > Hidden Stainless Steel Fasteners
- > 1 1/2" Square Edge Balusters and Square Edge Posts
- 5" Standard Newel Cover; 6", 8", 10" and 12" Optional
- > Multiple Newel Caps Available
- Painting is not necessary, but can be painted –
 No dark colors LRV 55 or greater
- > In House Custom Radius Capability



Color Selection for HPC CoA Application SPA Project #: 2021-22 Barkhorn (17 Webb)

Date	Revision / Submission
12/9/21	HPC Submission (Initial Release)



Partial Front Elevation



GAF TIMBERLINE HDZ SHINGLES PEWTER GRAYROOF SHINGLES



BENJAMIN MOORE
WINDHAM CREAM (HC-6)
SIDING AND 2ND FLOOR PANELS



SHERWIN WILLIAMS EXTRA WHITE (SW 7006) ALL TRIM COMPONENTS

METAL ROOFING SYSTEMS, INC. REGAL WHITE GUTTERS

REGAL WHITE





Partial Rear Steps Elevation



AERATIS HERITAGE T&G PORCH FLOORING BATTLESHIP GRAY REAR STEPS



Catalog of Existing Windows and Exterior Doors and Proposed Modifications 17 Webb Avenue, Ocean Grove

Notes:

This document was prepared by Andrea Fitzpatrick, AIA of Shore Point Architecture. To the best of her professional knowledge, the windows / exterior doors deemed historically significant are identified. If a historically significant window/door is proposed for removal as part of this application, the window / exterior door tag number is highlighted in yellow, below. A "condition report" for these windows / exterior doors, if required by the HPC, should be prepared and submitted by Others and is not included as part of this document.

Date	Revision / Submission
12/9/21	HPC Submission (Initial Release)



Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
101	¾ clear glass	2'-8"x7'-0"	Clear glass /	N	Υ	N	"Simpson" ½ clear
	in flush door		wood				glass, mahogany.
	slab						Match exist size.


Existing Photo (Interior)



Existing Photo (Exterior)



Proposed Replacement "Simpson" model #114





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>102</mark>	double-hung	2'-4"x5'-2"	Clear glass /	Υ	Υ	N	Andersen 400s
	1:1		wood				custom size
							(match exist), full
							frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement Andersen 400s DH 2:2 Custom





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
103	double-hung 1:1	1'-6"x5'-2"	Clear glass / wood	Y	Y	N	Andersen 400s custom size
							(match exist), full
							frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement Andersen 400s DH 2:2 Custom





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
104	picture	4'-0"x5'-2"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, picture*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement
Andersen 400s Custom Picture Window





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>105</mark>	double-hung	1'-6"x5'-2"	Clear glass /	Υ	Υ	N	Andersen 400s
	1:1		wood				custom size (match
							exist), full frame,
							2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement Andersen 400s DH 2:2 Custom





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
106	34 clear glass in flush door slab	3'-0"x7'-0"	Clear glass / wood	N	Y	N	"Simpson" ½ clear glass, mahogany. Match exist size.

Photo (Interior)



Photo (Exterior)



Proposed Replacement: "Simpson" model #114





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Additional info
					Proposed	Opening	
107	Fixed with diamond lite pattern	3'-6"x2'-8"	Clear glass / wood	Y	N	N	Repair damaged components as required. Scrape, clean and repaint.

Photo (Interior)



Photo (Exterior)





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>108</mark>	(3) fixed w/	(3) 1'-6"x2'-8"	Clear glass /	Υ	N/A	N/A	Demolish (due to
	diamond lite		wood				construction of
	pattern						proposed addition)

Photo (Interior)



Photo (Exterior)





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>109</mark>	double-hung	2'-4"x5'-2"	Clear glass /	Υ	N/A	N/A	Demolish (due to
	2:2		wood				construction of
							proposed addition)

Photo (Interior)



Photo (Exterior)



Photo (Detail)





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
110	Half Glass Door with 4 lite, 2-panel wood frame	2'-6"x6'-5"	Clear glass / wood	N	N/A	N/A	Demolish (due to construction of proposed addition)

Photo (Interior)



Photo (Exterior)





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
111	double-hung 2:2	2'-4"x3'-0"	Vinyl Replacement	N	N/A	N/A	Demolish (due to construction of
							proposed addition)

Photo (Interior)



Photo (Exterior)






Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
112	double-hung	2'-4"x3'-0"	Vinyl	N	N/A	N/A	Demolish (due to
	1:2		Replacement				construction of
							proposed addition)

Photo (Interior)



Photo (Exterior)






Tag number	Туре	Size	Material	Significant	Replacement Proposed	Modified Opening	Replacement Info
113	Glider	2'-10"x2'-4"	Vinyl	N	Y	Y	Andersen 400s TW2032 DH, 2:2

Photo (Interior)



Photo (Exterior)







Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement
					Proposed	Opening	Info
<mark>114</mark>	double-hung	2'-4"x5'-2"	Clear glass /	Υ	Υ	Υ	Andersen 400s
	1:1		wood			(shorten	custom size
						only)	(match exist
							width), full
							frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing WIDTH (at Kitchen)

Photo (Interior)





Photo (Detail)

Proposed Replacement:











Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement
					Proposed	Opening	Info
<mark>115</mark>	double-hung	2'-4"x5'-2"	Clear glass /	Υ	Υ	Υ	Andersen 400s
	2:2		wood			(shorten	custom size
						only)	(match exist
							width), full
							frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing WIDTH (at Kitchen)


Photo (Interior)



Photo (Exterior)



Proposed Replacement:





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
116	double-hung 2:2	2'-4"x5'-2"	Clear glass / wood	Y	N/A	N/A	Remove and Infill Opening due construction of new stair

Photo (Interior)



Photo (Exterior)





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>117</mark>	double-hung 2:2	2'-4"x5'-2"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*


^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)



Photo (Exterior)







Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>118</mark>	double-hung	1'-6"x5'-2"	Clear glass /	Y	Y	N	Andersen 400s
	1:1		wood				custom size (match
							exist), full frame, 2:2,
							DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Additional Info
					Proposed	Opening	
119	Picture Diamond lite over clear glass	3'-10"x5'-3"	Clear glass / wood	Y	N	N	Repair damaged components as required. Scrape, clean and repaint.

Photo (Interior)



Photo (Exterior)





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
120	double-hung 1:1	1'-6"x5'-2"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*


^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)



Photo (Exterior)







Tag number	Туре	Size	Material	Significant	Replacement	Modified	Additional Information
					Proposed	Opening	
201	double-hung	1'-10"x5'-2"	Clear glass /	N	N/A	N/A	Remove and Infill
	1:1		wood				Opening

Photo (Interior) Photo (Exterior) Photo (Detail)





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
202	double-hung 1:1	3'-2"x5'-2"	Clear glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
203	double-hung 1:1	3'-2"x5'-2"	Clear glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)



Photo (Exterior)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
204	double-hung 1:1	3'-2"x5'-2"	Clear glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)



Photo (Exterior)







Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
205	double-hung 1:1	3'-2"x5'-2"	Clear glass / wood	N	Υ	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
206	double-hung 1:1	2'-8"x5'-2"	Clear glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*


^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)



Photo (Exterior)







Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
207	double-hung 1:1	2'-8"x5'-2"	Clear glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*


^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)



Photo (Exterior)







Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
208	double-hung 1:1	2'-8"x5'-2"	Clear glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)


Photo (Exterior)

Photo (Detail)











Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
209	¾ Glass	2'-8"x6'-8"	Wood	N	Υ	N	Andersen 400S
							FWH2668, SDL, 2wx3h

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>210</mark>	double-hung	2'-0"x4'-10"	Clear glass /	Y	Y	N	Andersen 400s
	2:2		wood				custom size (match
							exist), full frame, 2:2,
							DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)





Photo (Detail)

Proposed Replacement











Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>211</mark>	(2) French	2'-8"x6'-8"	Clear glass /	Υ	Υ	N	Andersen 400S
	Doors		wood				FWH hinged 2668, SDL,
	18 lite each						2wx3h

Photo (Interior)




Photo (Exterior)



Photo (Detail)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
212	double-hung 2:2	2'-0"x4'-10"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement






Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
213	Half Glass	2'-8"x6'-8"	Clear glass /	N	Υ	N	Andersen 400S
	Door		wood				FWH 2668,
	4 lite						SDL, 2wx3h

Photo (Interior)


Photo (Exterior)

Photo (Detail)











Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
214	double-hung 2:2	2'-4"x5'-2"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Additional Info
					Proposed	Opening	
215	Casement Diamond lite	1'-10"x2'-9"	Clear glass / wood	Y	N	N	Repair damaged components as required. Scrape, clean and repaint.

Photo (Interior)



Photo (Exterior)



Photo (Detail)



Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>216</mark>	double-hung	2'-4"x4'-6"	Clear glass /	Υ	N/A	N/A	To be removed due to
	2:2		wood				construction /
							placement of addition

NOTE: Glass is missing from both top and bottom sash.

Photo (Interior)



Photo (Exterior)



Photo (Detail)








Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
217	double-hung 2:2	2'-4"x4'-6"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>218</mark>	double-hung	2'-4"x4'-6"	Clear glass /	Y	Υ	N	Andersen 400s
	2:2		wood				custom size (match
							exist), full frame, 2:2,
							DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)




Photo (Exterior)



Photo (Detail)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>219</mark>	double-hung	2'-0"x3'-0"	Clear glass /	Υ	N/A	N/A	Remove and Infill
	2:2		wood				Opening

Photo (Interior)




Photo (Exterior)



Photo (Detail)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>220</mark>	Inswing Casement 4 lite	2'-0"x2'-0"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 4 lite, Awning*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)




Photo (Exterior)



Photo (Detail)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>221</mark>	double-hung	2'-6"x4'-10"	Clear glass /	Υ	Υ	N	Remove and Infill
	2:2		wood				Opening due to stair
							location

NOTE: Hardware has been removed


Photo (Interior)

Photo (Exterior)



Photo (Detail)







Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>222</mark>	double-hung 1:1	1'-6"x4'-11"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match
							exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

NOTE: Hardware Removed – not operational

Photo (Interior)

Photo (Exterior)


Photo (Detail)

Proposed Replacement











Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>223</mark>	double-hung 1:1	2'-6"x4'-11"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)


Photo (Exterior)

Photo (Detail)











Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>224</mark>	double-hung	1'-6"x4'-11"	Clear glass /	Υ	N/A	N/A	Remove and infill
	2:2		wood				opening


Photo (Interior)



Photo (Exterior)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>301</mark>	double-hung 2:2	2'-4"x3'-10"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Photo (Detail)





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>302</mark>	double-hung	2'-4"x3'-10"	Clear glass /	Υ	Υ	Υ	Andersen 400S
	2:2		wood				FWH2068, SDL, 2wx3h

Photo (Interior)



Photo (Exterior)



Photo (Detail)





Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
303	double-hung 2:2	2'-4"x3'-11"	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)




Photo (Exterior)



Photo (Detail)



Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>304</mark>	French Doors	(2) 1'-3"x5'-6"	Clear glass /	N	Υ	Υ	Andersen 400s 24310,
	3 lite each		wood				full frame, 2:2, DH*
							(maintain exist. head
							ht)

Photo (Interior)







Photo (Detail)











Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>305</mark>	French Doors 3 lite each	(2) 1'-3"x5'-6"	Clear glass / wood	N	Y	Y	Andersen 400s 24310, full frame, 2:2, DH* (maintain exist. head ht)

Photo (Interior)


Photo (Exterior)

Photo (Detail)

Proposed Replacement









Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
<mark>306</mark>	double-hung	2'-4"x5'-2"	Clear glass /	Υ	Υ	N	Andersen 400s
	2:2		wood				custom size (match
							exist), full frame, 2:2,
							DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)


Photo (Exterior)

Photo (Detail)

Proposed Replacement









Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
307	Picture	3'-6"x2'-2"	Clear glass /	N	Υ	Υ*	Andersen 400s
			wood			Restore to	custom size (match
						original	exist), full frame, 4 lite,
						window size	Awning*
						(re: ext. trim)	

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Photo (Detail)





Tag	number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
						Proposed	Opening	
	<mark>308</mark>	double-hung 2:2	2′-8″x4′-10″	Clear glass / wood	Y	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

NOTE: Hardware Removed

Photo (Interior)


Photo (Exterior)

Photo (Detail)

Proposed Replacement









Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
309	Picture 8 lite	3'-0"x1'-10"	Obscured glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 8 lite, Picture*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)


Photo (Exterior)

Photo (Detail)

Proposed Replacement









Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
310	Awning 2 lite	2'-0"x1'-10"	Clear glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 4 lite, Awning*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.

Photo (Interior)



Photo (Exterior)





Photo (Detail) Proposed Replacement





Tag number	Туре	Size	Material	Significant	Replacement	Modified	Replacement Info
					Proposed	Opening	
311	double-hung 2:2	3'-0"x3'-9"	Newer Clear glass / wood	N	Y	N	Andersen 400s custom size (match exist), full frame, 2:2, DH*

^{*} If the window replacement is approved by the HPC, the interior window trim is to be removed so contractor can verify existing window frame sizes to ensure new windows (custom size, as required) match existing.


Photo (Interior)



Photo (Exterior)



Proposed Replacement





	New \	Windows in new ope	nings at Proposed Addition	
Tag number	Туре	Size	Proposed Window	Proposed Window Image
121	double-hung 2:2	2'-2"x3'-4"	Andersen 400s TW2032	
122	French Door 3 lite	2'-6"x6'-8"	"Simpson" ½ clear glass, mahogany.	
123	double-hung 2:2	2'-2"x3'-4"	Andersen 400s TW2032	
225	double-hung 2:2	2'-2"x4'-6"	Andersen 400s TW2042	



	New \	Windows in new oper	nings at Proposed Addition	
226	double-hung 2:2	2'-2"x4'-6"	Andersen 400s TW2042	

Condition Report for Significant Windows and Exterior Doors

17 Webb Avenue, Ocean Grove

Type background Interior In			ns	Summary of the	Condition of	Significan	ry of the Condition of Significant Windows and Doors	d Doors		
Windows and doors facing the streets (corner lot) Exterior Tag Proposal condition Operating condition Exterior Tag Restore Medium Fixed 217 Restore Medium Fixed 218 Restore Medium Fixed 220 Replace Good Opens/shuts OK Aging 306 Replace Good Opens/shuts OK Aging 114 Replace Good Opens/shuts OK Aging 115 Replace Good Opens/shuts OK Aging 116 Replace Good Opens/shuts OK Aging 116 Replace Good Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 224					17 Web	b Avenue				
Proposal Interior Operating condition Exterior Tag Restore Medium Fixed Aging 217 Restore Medium Fixed Aging 218 Restore Medium Fixed Aging 220 Restore Medium Fixed Aging 220 Replace Good Opens/shuts OK Aging 306 Replace Good Opens/shuts OK Aging 115 Replace Good Opens/shuts OK Aging 116 Replace Medium Difficult to open Aging 216 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging Notes: Replace Medium<		Windows and	doors facing	the streets (corner	lot)		Windows and	doors tha	t do not face the	streets
Proposal condition Operating condition condition Tag Restore Medium Fixed Aging 217 Restore Poor Does not open Aging 217 Replace Good Opens/shuts OK Aging 306 Replace Good Opens/shuts OK Aging 114 Replace Good Opens/shuts OK Aging 115 Replace Good Opens/shuts OK Aging 116 Replace Good Opens/shuts OK Aging 116 Replace Good Opens/shuts OK Aging 216 Replace Good Opens/shuts OK Aging 216 Replace Medium Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace			Interior		Exterior			Interior		
Restore Medium Fixed Aging 217 Restore Poor Does not open Aging 218 Restore Medium Fixed Badly aged 220 Replace Good Opens/shuts OK Aging 306 Replace Good Opens/shuts OK Aging 114 Replace Good Opens/shuts OK Aging 115 Replace Good Opens/shuts OK Aging 116 Replace Good Opens/shuts OK Aging 116 Replace Medium Difficult to open Aging 216 Replace Medium Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging Notes: Replace Medium Does not open Aging Notes: Replace	Tag	Proposal	condition		condition	Tag	Proposal	condition	Operating condition Exterior condition	Exterior condition
Restore Poor Does not open Aging 218 Restore Medium Fixed Badly aged 220 Replace Good Opens/shuts OK Aging 306 Replace Good Opens/shuts OK Aging 114 Replace Good Opens/shuts OK Aging 115 Replace Good Opens/shuts OK Aging 116 Replace Good Opens/shuts OK Aging 116 Replace Medium Opens/shuts OK Aging 216 Replace Medium Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging Notes: Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace	107	Restore	Medium	Fixed	Aging	217	Replace	Poor	Difficult to open	Aging
Restore Medium Fixed Badly aged 220 Replace Good Opens/shuts OK Aging 306 Replace Good Opens/shuts OK Aging 114 Replace Good Opens/shuts OK Aging 115 Replace Good Opens/shuts OK Aging 116 Replace Good Opens/shuts OK Aging 108 Replace Good Opens/shuts OK Aging 116 Replace Medium Opens/shuts OK Aging 216 Replace Medium Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging Notes: Replace Medium Difficult to open Aging Notes: Replace	119	Restore	Poor		Aging	218	Replace	Poor	Does not open	Badly aged
Replace Good Opens/shuts OK Aging 306 Replace Good Opens/shuts OK Aging 114 Replace Good Opens/shuts OK Aging 115 Replace Good Opens/shuts OK Aging 115 Replace Medium Difficult to open Badly aged 109 Replace Good Opens/shuts OK Aging 116 Replace Medium Opens/shuts OK Aging 215 Replace Medium Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes: <	215	Restore	Medium		Badly aged	220	Replace	Poor	Difficult to open	Badly aged
Replace Good Opens/shuts OK Aging 308 Replace Good Opens/shuts OK Aging 114 Replace Good Opens/shuts OK Aging 108 Replace Good Opens/shuts OK Badly aged 109 Replace Good Opens/shuts OK Aging 106 Replace Medium Opens/shuts OK Aging 216 Replace Medium Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes:	102	Replace	Good		Aging	306	Replace	Medium	Does not open	Aging
Replace Good Opens/shuts OK Aging 114 Replace Good Opens/shuts OK Aging 115 Replace Good Opens/shuts OK Badly aged 108 Replace Good Opens/shuts OK Aging 116 Replace Medium Opens/shuts OK Aging 216 Replace Medium Opens/shuts OK Badly aged 221 Replace Medium Opens/shuts OK Badly aged 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Opens/shuts OK Aging 224 Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes:	103	Replace	Good		Aging	308	Replace	Poor	Difficult to open	Aging
Replace Good Opens/shuts OK Aging 115 Replace Medium Difficult to open Badly aged 108 Replace Good Opens/shuts OK Aging 116 Replace Medium Difficult to open Aging 216 Replace Medium Opens/shuts OK Badly aged 219 Replace Medium Opens/shuts OK Badly aged 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Does not open Coming apart Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes:	104	Replace	Good	Opens/shuts OK	Aging	114	Shorten	Medium	Does not open	Badly aged
Replace Medium Difficult to open Badly aged 108 Replace Good Opens/shuts OK Aging 116 Replace Medium Difficult to open Aging 216 Replace Medium Opens/shuts OK Aging 219 Replace Medium Opens/shuts OK Badly aged 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Difficult to open Coming apart Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes:	105	Replace	Good		Aging	115	Shorten	Medium	Difficult to open	Badly aged
Replace Good Opens/shuts OK Badly aged 109 Replace Good Opens/shuts OK Aging 116 Replace Medium Difficult to open Aging 216 Replace Medium Opens/shuts OK Badly aged 219 Replace Medium Opens/shuts OK Aging 224 Replace Poor Difficult to open Coming apart 224 Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes:	117	Replace	Medium	Difficult to open	Badly aged	108	Demolish/infill	Poop	Fixed	poo9
Replace Good Opens/shuts OK Aging 116 Replace Medium Difficult to open Aging 216 Replace Medium Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 221 Replace Moor Difficult to open Coming apart 224 Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes:	118	Replace	Good	Opens/shuts OK	Badly aged	109	Demolish/infill	Poor	Difficult to open	Aging
Replace Medium Difficult to open Aging 216 Replace Medium Opens/shuts OK Badly aged 219 Replace Medium Opens/shuts OK Aging 221 Replace Medium Opens/shuts OK Aging 224 Replace Medium Difficult to open Coming apart Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Badly aged Notes:	120	Replace	Good	Opens/shuts OK	Aging	116	Demolish/infill	Poor	Difficult to open	Badly aged
Replace Medium Opens/shuts OK Aging 219 Replace Medium Opens/shuts OK Badly aged 221 Replace Medium Opens/shuts OK Aging 224 Replace Poor Difficult to open Coming apart Notes: Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Badly aged Notes:	210	Replace	Medium	to open	Aging	216	Demolish/infill	Poor	Does not open	Coming apart
Replace Medium Opens/shuts OK Badly aged 221 Replace Medium Opens/shuts OK Aging 224 Replace Poor Difficult to open Coming apart 224 Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Badly aged Population	211	Replace	Medium		Aging	219	Demolish/infill	Medium	Opens/shuts OK	Aging
Replace Medium Opens/shuts OK Aging 224 Replace Poor Difficult to open Coming apart Notes: Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Badly aged	212	Replace	Medium	Opens/shuts OK	Badly aged	221	Demolish/infill	Poor	Does not open	Badly aged
Replace Poor Difficult to open Coming apart Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Notes: Replace Medium Difficult to open Badly aged	214	Replace	Medium		Aging	224	Demolish/infill	Good	Opens/shuts OK	Aging
Replace Medium Does not open Aging Notes: Replace Medium Difficult to open Aging Aging Replace Medium Difficult to open Badly aged	222	Replace	Poor		Coming apart					
Replace Medium Difficult to open Aging Replace Medium Difficult to open Badly aged	223	Replace	Medium	Does not open	Aging	Notes:		ed as "Fixed"	are double-hung with	one operating sash
Replace Medium Difficult to open	301	Replace	Medium	to open	Aging		Only windows in the	lefthand tab	le face the street	
	303	Replace	Medium		Badly aged					
Replace with door Medium Difficult to open	302	Replace with door	Medium	Difficult to open	Aging					

NOTE: This document was prepared by Homeowner, Ivan Barkhorn.

17 Webb Ave. Condition Report

22 February 2022 Joe Wierzbinsky and Jenny Shaffer

NOTE: Siding and window surrounds not considered because not visible for inspection

GENERAL VIEWS (west and north sides cannot be photographed)



south façade



east façade



southwest corner



northeast corner

FIRST FLOOR PORCH: columns and railings

GENERAL COMMENTS:

- conditions must also be inspected by commissioners themselves
- three historic columns and one historic half-column (the southeast corner column is a modern replacement) numbered 1-5 from southwest to northeast (#3 is replacement)
- unusual, fluted, Tuscan-esque columns in poor to fair condition
- shafts appear plastered/patched and over-painted; some shafts have splits; some abaci split and/or broken; some bases split and/or broken
- note pent construction and various railings and how they relate to column shafts
- <u>historic railings in poor to fair condition</u>; some top and bottom rails compromised; some balusters partially knocked loose





Column #1: fair





Column #2: poor (abacus split/rotted; column split at railing connection)

(Column #3: modern replacement/not pictured)





Column #4 and #5 half-column to left on east side: poor (visible splits on north side) and fair



south railing: fair (note connection to column)





east railing, south to north: poor to fair

WINDOWS – GENERAL COMMENTS

- the great majority of the numerous windows in the house are historic
- they chart the the additive history of the structure, and thus date from the later decades of the nineteenth century into the first decades of the twentieth century
- they are, in general, in good/very good condition: retain/repair
- the majority of historic windows show no visible damage; a few are missing hardware
- the applicant kindly provided a window catalogue that includes photos of the windows as numbered on their elevations; we follow this numbering
- we took photos of every window (and door), but ask that commissioners refer to the applicant's catalogue for images; we can distribute more images if requested by commissioners
- our notes follow: <u>please compare them to the designations and comments provided by the applicant in the window catalogue</u>
- * indicates applicant has asked to either replace, demolish, or change dimensions of opening, and thus these windows are to be discussed by board

FIRST FLOOR WINDOWS

```
*102 – historic 1/1: retain (applicant wants to replace)
```

*104 – large picture window has historic surround/molding identical to historic windows (perhaps original entryway or double window modified?): retain (applicant wants to replace)

*105 – historic 1/1: retain (applicant wants to replace)

107 – historic diamond lite pattern window: retain as applied for

*108- historic 3 diamond lite pattern windows: retain? (applicant wants to demolish)

*109 – historic 2/2: retain? (applicant wants to demolish)

111 - vinyl window: not historic

112 - vinyl window: not historic

113 – vinyl window: not historic

*114 – historic 1/1: retain (applicant wants to shorten)

*115 – historic 2/2: retain (applicant wants to shorten)

*116 – historic 2/2: retain? (applicant wants to demolish)

*117 – historic 2/2: retain (applicant wants to replace)

*118 – historic 1/1: retain (applicant wants to replace)

119 – historic diamond lite over clear glass picture window: retain as applied for

*120 – historic 1/1: retain (applicant wants to replace)

^{*103 –} historic 1/1: retain (applicant wants to replace)

SECOND FLOOR WINDOWS

*201-208: older 1/1 wood windows that enclose what was once an open porch

- these wider windows are more modern than other wood windows in house
- question of date of enclosure to be discussed
- question of their removal goes beyond their condition?
- they are in generally good condition
- they are at times ill-fitting (see image)



- *210 historic 2/2: retain (applicant wants to replace)
- *212 historic 2/2: <u>retain</u> (applicant wants to replace)
- *214 historic 2/2: retain (applicant wants to replace)
- 215 diamond casement: retain as applied for
- *216 historic 2/2; frame missing glass: retain? (applicant wants to demolish)
- *217 historic 2/2: retain (applicant wants to replace)
- *218 historic 2/2: retain (applicant wants to replace)
- *219 historic 2/2: retain? (applicant wants to demolish)
- *220 historic 4-lite casement: retain (applicant wants to replace)
- *221 historic 2/2: retain/replace missing hardware (applicant wants to replace)
- *222 historic 1/1: retain/replace missing hardware (applicant wants to replace)
- *223 historic 1/1: retain (applicant wants to replace)
- *224 historic 1/1: retain (applicant wants to infill)

NOTE: unnumbered second floor window, now in interior, opened into porch before enclosed



THIRD FLOOR WINDOWS

- *301 historic 2/2: retain (applicant wants to replace)
- *302 historic 1/1: retain (applicant wants to modify)
- *303 historic 2/2: retain (applicant wants to replace)
- *306 historic 2/2: retain (applicant wants to replace)
- *307 current window not historic/older; opening like one on first floor?
- *308 historic 2/2: <u>retain</u> (applicant wants to replace)
- *309 8-lite textured glass/age unclear (applicant wants to replace)
- *310 awning window/age unclear (applicant wants to replace)
- *311 2/2 age unclear (applicant wants to replace)

DOORS – GENERAL COMMENTS

- there are a number of old doors, some of which are clearly or possibly historic
- their ages are points for discussion
- most not from original house, but from later changes/additions to it
- doors generally are in good condition: retain/restore, depending on age
- photos of doors in window catalogue except where included below

*101 – front door with beveled glass appears historic; older storm/screen door (applicant asks to replace)



*106 – side door with beveled glass appears historic; another older storm door(applicant asks to replace)



*110- Half-glass door appears historic/older wooden storm door (applicant asks to demolish)



- *209 historic wooden door, 3/4 glass, to porch (applicant asks to replace)
- *211 historic narrow double French doors, possibly from original house
 - note: another pair, also in good condition, in current interior opens into the enclosed porch



doors to second floor porch



second pair in room, now interior, once opened to porch

*213 – older wood 1/2 glass door (applicant asks to replace)

304 – newish sort of French doors: not historic 305 – newish sort of French doors: not historic

ZOOM CALLS

9:15am – 17 Webb Avenue – Andrea Fitzpatrick

Tech Review Team – Deb Osepchuk, Lucinda Heinlein and Jeff Ruddell

Deferred from 3.8.22 regular meeting to discuss proposal issues

Low slope hip roof – new roof 4:12 pitch – visually similar – NO ALCOVE –

AC condenser gone

Not enough room in side yard for A/C – addition has shrunken to allow for room. Pushed in 1 foot so now 4' 10" instead of 5' 10" which allows A/C in side yard without encroaching over the property line. Only allowed 30" in front yard area most condensers are taller than 30'' - 2 lower units with 30" fence but could do 1 unit with taller fence. Up to Andrea and the Client with regard to condensers per Tech.

East elevation shared to show where condenser(s) will be located. They will utilize 2 smaller condensers.

Because we have pulled the addition back the roof is now bracketed instead of a column dropping down because roof overhang is not as deep anymore. Will provide a detail for the bracket (angle bracket)

Dormer – pulled from the project over 3rd story door.

Porch – originally tried to preserve pent roof – having issues with ventilation below the porch. Based on condition of porch – better solution is to take porch off and reconstruct. Pent roof is falling off right now. Columns are in poor condition. Rather than trying to preserve. Preferred solution. Will provide additional photos of the pent roof.

Windows & Doors – 55 windows & doors – 6 of the windows are requesting to be removed for this addition.

108 – triple diamond – 109 deep in alcove – 110 door into kitchen – 111 vinyl window in alcove – 112 vinyl window is area of addition – 216 double hung 2/2 clear glass wood in area of addition in bad shape.

Discussion takes place with regard to window 108 – not sure when it was installed but not original to the 1800's structure.

46 windows requesting to replace out of 49 windows – not acceptable to the Board – in revised submission reduced number down to 22 windows which need to be replaced – not visible locations 8 of them enclose the 2nd floor porch.

Windows reviewed elevation by elevation. Windows seeking to replace and seeking to keep.

Eliminiate siding replacement – proposing residing 2 areas of this house on the east side 2-story portion of the house.

The north side of the house something can talk about – removing roof reframing it and putting an addition all 1 plane and alignes with the plane of the house. Would prefer to reside this area with hardiplank to match the original clap board portion. Will have to re-evaluate siding.

How do you resolve the trim pieces? Solution will never be perfect you can only do best you can come up with a detail where you project the casing past the vinyl and instead of butting up run vinyl behind it.

Deborah Osepchuk, Chair Lucinda Heinlein, 1st Vice Chair Jeffery Rudell, 2nd Vice Chair Steven R. Tombalakian, Esq., HPC Attorney Ronald D. Cucchiaro, Esq., HPC Attorney Tracey James, Administrative Officer/Secretary



Kurt Cavano, Member Douglas MacMorris, Member Jenny Shaffer, Member Joseph Wierzbinsky, Member Douglas McKeon, Alternate No. 1 James McNamara, Alternate No. 2

OFFICE OF THE HISTORIC PRESERVATION COMMISSION

2201 Heck Avenue (Engineering/Planning Dept) - Neptune NJ 07753 (732) 897-4162 Ext. 200 tjames@neptunetownship.org

February 9, 2022

Sent via e-mail abf@shorepointarch.com and First Class Mail

Andrea Fitzpatrick, AIA 108 S. Main Street Ocean Grove, NJ 07756

RE:

HISTORIC PRESERVATION COMMISSION APPLICATION NO. HPC 2021-215 BLOCK 228 LOT 13 ALSO KNOWN AS 17 WEBB AVENUE

Dear Applicant:

Please be advised the above mentioned application has been reviewed for completeness and the Application Review Team (Review Team) has determined that this application cannot be administratively approved. Therefore, you are hereby notified that your application has been scheduled for a virtual public hearing before the Historic Preservation Commission. Your application has been scheduled for a virtual public hearing/meeting on **Tuesday, March 8, 2022 at 7:00 PM**. The meeting will be held virtually via Zoom. Log-in and Participant information is as follows:

Topic: HPC Regular Meeting

Time: Mar 8, 2022 07:00 PM Eastern Time (US and Canada)

Join Zoom Meeting

https://us02web.zoom.us/i/84839156633?pwd=c3ZoR0RYYWdQd1ZyTTRMQ1FJcFgwUT09

Meeting ID: 848 3915 6633

Passcode: 961544 One tap mobile

- +13126266799,,84839156633# US (Chicago)
- +16465588656,,84839156633# US (New York)

Dial by your location

- +1 312 626 6799 US (Chicago)
- +1 646 558 8656 US (New York)
- +1 301 715 8592 US (Washington DC)
- +1 346 248 7799 US (Houston)
- +1 669 900 9128 US (San Jose)
- +1 253 215 8782 US (Tacoma)

Meeting ID: 848 3915 6633

Find your local number: https://us02web.zoom.us/u/kiKwga365

Preliminary Review Notes

Below, please find the Application Review notes. Please understand that this is a preliminary review. It includes, but is not limited to, the observations on the following pages concerning your project. In no event shall this preliminary review constitute an approval. Neither the Applicant nor the Review Team is bound by this review. Also, these comments do not preclude additional information requests, comments, or concerns from HPC members before or at the virtual hearing/meeting. The Applicant and/or the Representative of the Applicant should carefully review the notes below and be prepared to discuss these items and/or provide any additional information requested.

Classification - Key Structure

As per Ocean Grove Historic District Architectural Guidelines for Residential Structures, Section III, p. 9, this property is considered a Key Structure by date. Key structures include those dwellings originally constructed between the 1880s and 1910 and consist primarily of Eastlake, Gothic Revival, Italianate, Stick Style, Queen Anne, and Early Summer Cottage Vernacular styles. Applications for work on key and contributing structures are most carefully scrutinized during the HPC review process.

Description of Work

Applicant is proposing various alterations as outlined below.

Conforming Items:

1) Addition / Alterations:

- a) Remove the roof of the existing (newer) two-story portion at the rear of the structure. The roof on the existing rear addition appears non-historic in shape and slope. The Tech Committee does **not oppose** removing this roof.
- b) Infill the open air first floor "alcove" with a one-story addition. The Tech Committee agreed that the "alcove" at the rear addition is a viable location for the proposed expansion of the property. **Conforming.**
- c) Expand the first and second floor at the rear to align with the east face of the existing second floor cantilever projection. The expansion of this historic property at this rear location is **Conforming.**

2) Siding replacement, exterior trim replacement, other exterior upgrades:

a) Roofing: Removal and replacement of existing roof shingles with new "Timberline" asphalt roof shingles. The proposed roof material and color are **Conforming**.

3) Porch upgrades:

- a) The existing porch pent roof is in poor condition and will be repaired / restored. Conforming.
- b) New T&G mahogany porch flooring is proposed as the existing flooring has buckled due to the lack of airflow mentioned. T&G Mahogany for the front steps only. **Conforming.** Aeratis in Battleship Gray will be used for the rear stair. **Conforming.**
- c) The existing brick stair on south elevation is to be replaced with new wood framed stair with mahogany treads and CPVC risers and trim. **Conforming.**
- d) Existing wood railings are in very poor condition and we propose to replace them with a new custom wood railing system, 30" height, with 5" sq. CPVC "Versatex" newel wraps, where indicated. In discussion with Andrea Fitzpatrick, these materials apply only to first floor railings/newels. **Conforming.** Balusters will be CPVC, 4" on center, painted. **Conforming.**
- e) Existing second and third floor porches to receive new "Intex" 36" height railings, as indicated; new fiberglass decking; new trim; new PVC beadboard ceilings (2nd floor); new 5" square CPVC "Versatex" newel wraps. **Conforming.**

4) Site Improvements

- a) Removal and replacement of concrete walkway on east side of house, as indicated. In discussion with Andrea Fitzpatrick, this refers to the paved areas near the rear, street-side of the property, not to the public sidewalk. Conforming.
- b) Removal of vinyl stockade fence along Beach Avenue, as mentioned above. Conforming.
- c) Demolish existing outdoor shower on east side, facing Beach Avenue. Conforming.

5) Other

a) Construct new gable roof dormer on third floor, east elevation, to allow for the headroom required for the installation of a new door to access the existing uncovered third floor balcony. **Conforming.**

Conforming Items Requiring Discussion and Non-Conforming Items:

1) Addition / Alterations:

a) Construct a new 4:12 hip roof above this expanded rear two-story area. The proposed new roof at the rear of the property is **Conforming in part**: the pitch is deemed appropriate. See below.

The new roof to contain an alcove in the center for an AC condenser (will not be visible from the street) to allow for the relocation of an existing AC condenser that is currently positioned in the east side yard (street facing) but is concealed from street view by a six-foot height vinyl stockade fence (to be removed). The inclusion of a hidden "roof alcove" or "well" behind a parapet in the roof was deemed a non-historic roof form. Further, the necessity of such a non-conforming configuration was questioned since the conditions of this "necessity" were created by proposed alterations at the ground floor. The Tech Committee recognizes the property has no other viable location beyond where the A/C condenser is currently located. They strongly suggest the unit remain where it is (at grade, at the rear side of the building) and simply be shielded by an appropriate lattice enclosure once the existing stockade fence is removed. **Non-Conforming.**

a) Construct a new one-story addition on the east side of the house that includes a covered entry to a side door. The design of the proposed one-story addition was found to be **Conforming** but the proposed parameters of this structure creates a non-conformity in the placement of the A/C condenser (see above). This element of the design will be dependent on finding a conforming placement for the existing A/C unit. **To be discussed.**

2) Siding replacement, exterior trim replacement, other exterior upgrades:

In 1992, the existing house was approved for installation of vinyl siding over (what the applicant documented as) 5" exposure wood clapboard.

Small sections of the vinyl were recently lifted and various exposures of 4" and 4-1/2" were found.

- a) As part of this application, we propose the removal of all existing siding layers and replacement with new Hardie Plank clapboard siding, smooth finish, 4-1/2" exposure.
 - We understand the HPC will require a site visit to arrange for the observation of original wood clapboard in select areas and we will schedule this at the appropriate time. The determination as to whether the existing historic cladding may be removed and replaced with Hardie Plank cannot be made until a site visit establishes the condition of said historic cladding. **Pending Inspection.**
- b) After removing select areas of aluminum coil stock from existing windows, it was determined that the existing window casings contain 4-1/2" (actual) width legs. We propose removal and replacement of all existing window and door casings and replacement with new PVC trim components to match the existing profile sizes (4-1/2"). Window and door casing are often part of the historic material. These items must be inspected before we can discuss proposed replacement materials. Pending Inspection.
- c) Additionally, new CPVC corner boards, fascias, rakes, and other trim components are proposed as indicated. **Pending Inspection.**
- d) Gutters: Includes removal of existing "k-style" gutters and replacement with new prefinished aluminum half-round gutters and round leaders. White, half-round gutters are conforming. Please amend your application to include a gutter and leader schedule indicating where on the elevation(s) these items will be located. The gutter and leader schedule will be provided as a condition of approval should the HPC vote in favor of the application.

3) Window and Door Replacements/Removal:

Please refer to the included "Window Catalog" for a detailed outline of the existing windows and doors and the modifications proposed.

- a) Consideration of proposed window repair, restoration, and/or replacement is dependent on a site visit and subsequent report from HPC Members. **Pending inspection.**
- b) A number of windows are proposed to be eliminated, shortened, or moved. An inspection is required before these items can be addressed. **Pending inspection.**

The rhythm of the fenestration on the second floor enclosed porch is not historic. The question before the HPC Commission will be whether this rhythm should be replicated (to indicate non-historic modifications to the project over the years) or brought into conformity with more historically appropriate fenestration spacing. **To be discussed.**

The proposed under-window decorative panels were deemed historically inappropriate. A number of historic photos of this house are present in the HPC file. These where shared with Andrea Fitzpatrick. One shows clapboard beneath these enclosed-porch windows. Another shows what may be vertical vinyl strips. **To be discussed.**

A 1/2 glass, wooden Simpson door, with inset single panel, is proposed. An inspection of the existing door is needed to determine whether it is historic and can be replaced. **Pending inspection.**

Anderson French wood, in-swing patio doors are specified in other locations. The door style and placement is **Conforming; however, conditional on the outcome of site inspection.**

4) Porch upgrades:

- a) At first floor front (wrap around) porch, we propose to remove and replace the existing round fluted columns. The corner column was replaced in 2014 by Ocean Grove hardware with a new Permacast fluted column to match the historic design. All other columns are wood (possibly) original and are in poor condition (see photo). Consideration of the proposed column replacements is dependent on an inspection and subsequent condition report by HPC. Pending Inspection.
- b) New 16"x 8" decorative foundation vents will be installed in the (currently) fully enclosed masonry porch foundation wall, as there is limited airflow below the porch flooring. Proposed vents appear Conforming in size and location; however, a catalog cut for this item must be provided as a condition of any approval should the HPC find in favor of this application.

5) Site Improvements:

a) Removal and relocation of AC condenser from east side yard (along Beach Ave.) to roof at rear. **Non-conforming (see above.)**

Additional Request

PLEASE PROVIDE THIS OFFICE WITH ELEVEN (11) COPIES OF ALL PLANS, SPECIFICATIONS/CUT SHEETS, AND PHOTOS NO LATER THAN FRIDAY, FEBRUARY 25, 2022 FOR DISTRIBUTION TO EACH OF THE COMMISSION MEMBERS.

If any changes are made to your application after you have been placed on the agenda, or if you fail to produce any of the items requested by the Commission, your hearing will be deferred to the next available meeting.

It is highly recommended that you attend this virtual hearing in order to address any questions or concerns the Commission may have. An Architect, Contractor, or Attorney may accompany you, or you may appoint a representative in the event you are unable to attend/participate. Please be advised, your absence or lack of participation in the virtual meeting may cause your application to be deferred.

For your convenience, the Ocean Grove Historic District Guidelines for Residential Structures can be found online at www.neptunetownship.org.

The HPC thanks you for your cooperation and support in maintaining the integrity and character of the Ocean Grove, a registered National and State Historic District. Should you have any further questions or concerns please feel free to contact me at (732) 897-4162, extension 200 or via email tiames@neptunetownship.org.

Cordially,

Tracey James

HPC Administrative Officer/Secretary



Property Location: 17 WEBB AVE Application No: HPC2021-215
Application Date: 12/14/2021

HISTORIC PRESERVATION COMMISSION CERTIFICATE OF APPROPRIATENESS - INCOMPLETE

✓ AC UNIT	GATE	▼ RAILINGS	
✓ ADDITION	☐ GENERATOR	RETAINING WALL	
ARBOR	☐ GUTTERS & LEADERS	▼ ROOF	
AWNING	HOT TUB	SATELLITE DISH	
BALCONY	✓ LATTICE	☐ SHED	
CHIMNEY	☐ LIGHT FIXTURE	SHUTTERS	
✓ COLUMNS	☐ NEW CONSTRUCTION	✓ SIDING	
DECK	ORNAMENTATION	□ SIGN	
✓ DOOR REPLACEMENT	☐ OUTDOOR SHOWER	SKYLIGHT	
DRIVEWAY	PAINT	SOLAR	
EXTERIOR ALTERATIONS	PATIO	 STAIRS	
FENCE	PIERS	VENT	
☐ FLAGS/BANNERS	™ PORCH	□ WALKWAY	
FOUNDATION	PORCH FAN	₩ windows	
OTHER incomplete 2.2.22 / jeff's	notes will be sent in letter - tj note 2.4	.22	
PROPERTY IDENTIFICATION			
Property Address: 17 WEBB AVE			
Block: 228	Lot: 13	Qualifier:	
OWNER INFORMATION Name(s): BARKHORN, IVAN Address 1542 HIGH STREET BOULI	DER, CO 80304		
Phone: (732)774-6900		Email:	
APPLICANT INFORMATION			
Check if same as Owner			
Names(s): Andrea Fitzpatrick	Company:		
Address: 108 S Main St. OCEAN GR	· · ·		
Phone: (732)774-6900	Email: abf@shorepo	intarch.com	
PROPERTY INFORMATION			***************************************
Property Type?(check one)			
Single Family Multifamil	y: <u>0</u> Units Commercial	☐ Condo ☐ Mixed Use	
Architectural Period / Year Built:		Architectural Style:	*********
Demolition hearing required? YES	s 🔲 NO		
IF YES:you must apply for a Demolition		icate of Appropriateness	
Zoning Permit Acquired? TYES	NO N/A		
Zoning Permit ID# (from Zoning Perm	it)	DATE APPROVED:	

APPLICATION REVIEW NOTES:

The Review Team has deemed this application incomplete, as the Applicant has not submitted all required information to evaluate the project as described on the application and in the information sheet. The Review Team has identified general and specific deficiencies based on Neptune Township Land Development Ordinances and Ocean Grove Historic District Architectural Design Guidelines. Please understand that this is a preliminary review. It includes, but is not limited to, the observations below:.

Description of Work

1. Addition / Alterations:

Remove the roof of the existing (newer) two-story portion at the rear of the structure. The roof on the existing rear addition appears non-historic in shape and slope. The Tech Committee does **not oppose** removing this roof.

Infill the open air first floor "alcove" with a one-story addition. The Tech Committee agreed that the "alcove" at the rear addition is a viable location for the proposed expansion of the property. **Conforming.** Expand the first and second floor at the rear to align with the east face of the existing second floor cantilever

projection. The expansion of this historic property at this rear location is **Conforming**.

Construct a new 4:12 hip roof above this expanded rear two-story area. The proposed new roof at the rear of the property is **Conforming in part**: the pitch is deemed appropriate. See below.

The new roof to contain an alcove in the center for an AC condenser (will not be visible from the street) to allow for the relocation of an existing AC condenser that is currently positioned in the east side yard (street facing) but is concealed from street view by a six-foot height vinyl stockade fence (to be removed). The inclusion of a hidden "roof alcove" or "well" behind a parapet in the roof was deemed a non-historic roof form. Further, the necessity of such a non-conforming configuration was questioned since the conditions of this "necessity" were created by proposed alterations at the ground floor. The Tech Committee recognizes the property has no other viable location beyond where the A/C condenser is currently located. They strongly suggest the unit remain where it is (at grade, at the rear side of the building) and simply be shielded by an appropriate lattice enclosure once the existing stockade fence is removed. **Non-Conforming.**

Construct a new one-story addition on the east side of the house that includes a covered entry to a side door. The design of the proposed one-story addition was found to be **Conforming** but the proposed parameters of this structure creates a non-conformity in the placement of the A/C condenser (see above). This element of the design will be dependent on finding a conforming placement for the existing A/C unit. **To be discussed.**

2. Siding replacement, exterior trim replacement, other exterior upgrades:

In 1992, the existing house was approved for installation of vinyl siding over (what the applicant documented as) 5" exposure wood clapboard.

Small sections of the vinyl were recently lifted and various exposures of 4" and 4-1/2" were found.

As part of this application, we propose the removal of all existing siding layers and replacement with new Hardie Plank clapboard siding, smooth finish, 4-1/2" exposure.

We understand the HPC will require a site visit to arrange for the observation of original wood clapboard in select areas and we will schedule this at the appropriate time. The determination as to whether the existing historic cladding may be removed and replaced with Hardie Plank cannot be made until a site visit establishes the condition of said historic cladding. **Please contact the HPC Administrator and schedule a site visit. Pending** After removing select areas of aluminum coil stock from existing windows, it was determined that the existing window casings contain 4-1/2" (actual) width legs.

We propose removal and replacement of all existing window and door casings and replacement with new PVC trim components to match the existing profile sizes (4-1/2"). Window and door casing are often part of the historic material. These items must be inspected before we can discuss proposed replacement materials. **Pending** Additionally, new CPVC corner boards, fascias, rakes, and other trim components are proposed as indicated. **Pending Inspection.**

Gutters: Includes removal of existing "k-style" gutters and replacement with new prefinished aluminum half-round gutters and round leaders. White, half-round gutters are **Conforming**. Please amend your application to include a gutter and leader schedule indicating where on the elevation(s) these items will be located. **Incomplete**. Roofing: Removal and replacement of existing roof shingles with new "Timberline" asphalt roof shingles. The proposed roof material and color are **Conforming**.

3. Window and Door Replacements/Removal:

Please refer to the included "Window Catalog" for a detailed outline of the existing windows and doors and the modifications proposed. Consideration of proposed window repair, restoration, and/or replacement is dependent on a site visit and subsequent report from HPC Members. **Pending inspection.**

A number of windows are proposed to be eliminated, shortened, or moved. An inspection is required before these items can be addressed. **Pending inspection.**

The rhythm of the fenestration on the second floor enclosed porch is not historic. The question before the HPC Commission will be whether this rhythm should be replicated (to indicate non-historic modifications to the project

over the years) or brought into conformity with more historically appropriate fenestration spacing. **To be discussed.**

The proposed under-window decorative panels were deemed historically inappropriate. A number of historic photos of this house are present in the HPC file. These where shared with Andrea Fitzpatrick. One shows clapboard beneath these enclosed-porch windows. Another shows what may be vertical vinyl strips. **To be discussed.**

A 1/2 glass, wooden Simpson door, with inset single panel, is proposed. An inspection of the existing door is needed to determine whether it is historic and can be replaced. **Pending inspection.**

Anderson French wood, in-swing patio doors are specified in other locations. The door style and placement is **Conforming conditional on the site inspection.**

4. Porch upgrades:

At first floor front (wrap around) porch, we propose to remove and replace the existing round fluted columns. The corner column was replaced in 2014 by Ocean Grove hardware with a new

Permacast fluted column to match the historic design.

All other columns are wood (possibly) original and are in poor condition (see photo above). Consideration of the proposed column replacements is dependent on an inspection and subsequent condition report by HPC. **Incomplete.**

The existing porch pent roof is in poor condition and will be repaired / restored. Conforming.

New 16"x 8" decorative foundation vents will be installed in the (currently) fully enclosed masonry porch foundation wall, as there is limited airflow below the porch flooring. Proposed vents appear **Conforming** in size and location. Please provide a cat/cut of this item for the application. **Incomplete.**

New T&G mahogany porch flooring is proposed as the existing flooring has buckled due to the lack of airflow mentioned above. T&G Mahogany for the front steps only. **Conforming.** Aeratis in Battleship Gray will be used for the rear stair. **Conforming.**

The existing brick stair on south elevation is to be replaced with new wood framed stair with mahogany treads and CPVC risers and trim. **Conforming.**

Existing wood railings are in very poor condition and we propose to replace them with a new custom wood railing system, 30" height, with 5" sq. CPVC "Versatex" newel wraps, where indicated. In discussion with Andrea Fitzpatrick, these materials apply only to first floor railings/newels. **Conforming.** Balusters will be CPVC, 4" on center, painted. **Conforming.**

Existing second and third floor porches to receive new "Intex" 36" height railings, as indicated; new fiberglass decking; new trim; new PVC beadboard ceilings (2nd floor); new 5" square CPVC "Versatex" newel wraps. **Conforming.**

5. Site Improvements

Removal and replacement of concrete walkway on east side of house, as indicated. In discussion with Andrea Fitzpatrick, this refers to the paved areas near the rear, street-side of the property, not to the public sidewalk. **Conforming.**

Removal of vinyl stockade fence along Beach Avenue, as mentioned above. **Conforming.**Removal and relocation of AC condenser from east side yard (along Beach Ave.) to roof at rear. **Non-conforming** (see above.)

Demolish existing outdoor shower on east side, facing Beach Avenue. Conforming.

6. Other

Construct new gable roof dormer on third floor, east elevation, to allow for the headroom required for the installation of a new door to access the existing uncovered third floor balcony. **Conforming.**

Submitting Required Information:

Emailed submissions will not be accepted. The requested information can be submitted to the Commission Secretary, Tracey James, via hand delivery or standard mail. Please include a cover letter stating the reason for the submission or write "Response to Application Review" at the top of all your documents, be sure to also include your application number. The mailing address is as follows:

Tracey James, HPC Administrative Officer/Secretary Engineering/Planning Offices 2201 Heck Avenue Neptune, NJ 07753.

Tracey James, HPC Administrative Officer


IMPORTANT INFORMATION:

This application will remain incomplete until all requested information has been submitted. Once this office receives the required information, the Applicant Review Team will review your application again. If it is determined that some or all of the proposed work does not demonstrate compliance with the current Ocean

Grove Historic District Architectural Design Guidelines for Residential or Commercial Structures, you will be scheduled to appear before the full Historic Preservation Committee.

In accordance with Ordinance No. 16-32 Any person, firm or corporation that shall violate any provisions of this Ordinance shall, upon conviction thereof by any court authorized by law to hear and determine the matter, be fined such sum not exceeding \$2,000.00 as such court in its discretion may impose; or if the parties so convicted be a natural person, such person may be imprisoned for such term not exceeding 90 days as such court in its discretion may impose, or appear at community service not exceeding 90 days or any combination thereof as such court in its discretion may impose. Each day that such violation exists shall constitute a separate offense.

CC:



SIDI

RKHO \triangleleft


S CO

> TE PLAN, 'INFORMATION SIT **PROJE**

11/22/2021

2021-22

A-1 BARKHORN





ARKHORN RESIDENCE

Block: 228
Lot: 13

O7756 Stephen J. Carli


SHORS South Main Street, Ocean Grove, New Jersey 07750 Pr. 732.774.6900 F: 732.774.7250 www. shorepointarch.cor

FLOOR PLANS

DATE 11/22/21 ZONING SUB.-INITIAL RELEASE 11/22/21 ZONING SUB.-INITIAL RELEASE STATE STATE

JOB NUMBER 2021-22

A-3
BARKHORN



SID AN N 0 RKH \triangleleft

11/22/2021

BARKHORN