




#19



not changing this window small with color glass
#7
#12
Left Side of the house on Embury Ave


outside Look at
one of the windows
First Floor
Rotten wood and
can't open or close
the window
#12
Covered it
with
Primer
while waiting
for Permit
So it doesn't get
worst with water


Left sid house
looking towards next
house.
broken bathroom
windw, can't oper
or close
on the second floor
plus rotten wood.
#7



Right Side of the House on Pensilvenia Ave OG.
Broken
Can't open or close
#1
wood
#2
wood
#3 wood
#4
wood
#5
wood
#9
Vinyl
#10
#11
Not changing
Not changing
Vinyl
Same as 10
Vinyl
wood

Second Floor insid Pictures For the Windows




Second Floor Window on the corner right Sid of the house broken, can't open or close. From top of bo Hom

Right Side # 1



one of the broken windows on the Right side of the house second Floor bedrooms

2


#3
Right sid of the house
Second Floor
bedroom window
broken, can't oper
or cbse broken
glace, Rotten, wood.